PLAINTIFF'S EXHIBIT PX-756

EXPERIMENTAL 6-68 — INSPECTOR'S DAILY NARRATIVE — Tower A

CONTRACT NO.	CONTRACTOR	WEATHER
WTC 113-00	Mario + D' Bono	80's

Elev 253. Cleaning rust + scales from beams + columns

Built platform Elev 310 N.W Corner

A. Calabrese (INSPECTOR) — 8-12-69 (DATE) — 9-4:00 (SHIFT) — A (REVIEWED BY)

EXPERIMENTAL 6-68 — INSPECTOR'S DAILY NARRATIVE — Tower A

CONTRACT NO.	CONTRACTOR	WEATHER
WTC 113-00	Mario + Di Bono	80's

Scraping mill rust + scales from steel beams + cols Elev 253

Total personnel 5

A. Calabrese (INSPECTOR) — 8-11-69 (DATE) — 9-4:00 (SHIFT) — A (REVIEWED BY)

EXPERIMENTAL 6-68 — INSPECTOR'S DAILY NARRATIVE — Tower A

CONTRACT NO.	CONTRACTOR	WEATHER
WTC 113-00	Mario + D' Bono	70's

Elev 253-294 Cleaning rust + scales from beams + scales

A. Calabrese (INSPECTOR) — 8-15-69 (DATE) — 9-4:00 (SHIFT) — A (REVIEWED BY)

EXPERIMENTAL 6-68 — INSPECTOR'S DAILY NARRATIVE — Tower 'A'

CONTRACT NO.	CONTRACTOR	WEATHER
WTC 113-00	Mario + Di Bono	80's

Elev 294-284-253 - Cleaning rust + scales from cols + beams

A. Calabrese (INSPECTOR) — 8-13-69 (DATE) — 9:00-11:00 (SHIFT) — A (REVIEWED BY)

WTCI-513-P

EXPERIMENTAL 8-68

INSPECTOR'S DAILY NARRATIVE

CONTRACT NO.	CONTRACTOR	WEATHER
WTC 113-00	Mario & D'Bono	70's

Elev 294 - 2nd floor - Cleaning beams & Cols & spraying

A. Calabrese — INSPECTOR; 8-18-69 — DATE; 9-4:00 — SHIFT; A; REVIEWED BY

EXPERIMENTAL 8-68

INSPECTOR'S DAILY NARRATIVE

CONTRACT NO.	CONTRACTOR	WEATHER
WTC 113-00	Mario & D'Bono	70's

Received pipe scaffold and 1 Truck-load of Cafco material

A. Calabrese — INSPECTOR; 8-14-69 — DATE; 9-4:00 — SHIFT; A; REVIEWED BY

Tower A

EXPERIMENTAL 8-68

INSPECTOR'S DAILY NARRATIVE

CONTRACT NO.	CONTRACTOR	WEATHER
WTC 113-00	Mario & D'Bono	70's

Elev 294 - Fireproofing beams & cols
Elev 310 - Cleaning beams & cols
Elev 242 - Cleaning beams & cols

A. J. Calabrese — INSPECTOR; 8-20-69 — DATE; 9:00-4:00 — SHIFT; A; REVIEWED BY

Tower 'A'

EXPERIMENTAL 8-68

INSPECTOR'S DAILY NARRATIVE

CONTRACT NO.	CONTRACTOR	WEATHER
WTC 113-00	Mario & D'Bono	80's

Elev 294 - 310 - Cleaning & spraying beams & cols

Told T. Blackman to clean & put required thickness on

A. J. Calabrese — INSPECTOR; 8-19-69 — DATE; 9:00-4:00 — SHIFT; A; REVIEWED BY

INSPECTOR'S DAILY NARRATIVE

CONTRACT NO.	CONTRACTOR	WEATHER
113	Mario & Di Bono	

Tower B

2 plasterers, 4 laborers spray patch truck area 2-4 [illegible] 250

INSPECTOR: [illegible] DATE: 8/11/70 SHIFT: Day REVIEWED BY:

INSPECTOR'S DAILY NARRATIVE

CONTRACT NO.	CONTRACTOR	WEATHER
113-110 - TKCC 370	Mario & Di Bono, Star Circle, TKCC, Otis	

Bank "A" Tower "A"

TKCC forms caulking & cleaning approx 75% complete. Mario & Di Bono tentatively scheduled for Friday or Sat for Mark II spray will touch up w/ ceramic fiber.

Star Circle will remove [illegible] as necessary in 370 area

INSPECTOR: [illegible] DATE: 8/26/70 SHIFT: Day REVIEWED BY:

EXPERIMENTAL INSPECTOR'S DAILY NARRATIVE

Tower 'A'

CONTRACT NO.	CONTRACTOR	WEATHER
WTC-113-00	Mario & Di Bono	80's

Elev 284-294 - Fire-proofing cols & beams

Elev 253-242 - Cleaning of steel & spraying

Mario & Di Bono - ordered to stop spraying by Tishman because other trades refused to work on same level as spraying - to much dust.

INSPECTOR: A. J. Calabrese DATE: 8-22-69 SHIFT: 8⁰⁰-4⁰⁰ REVIEWED BY:

EXPERIMENTAL INSPECTOR'S DAILY NARRATIVE

Tower A

CONTRACT NO.	CONTRACTOR	WEATHER
WTC 113-00	Mario & Di Bono	80's

Elev 284-294 Fireproofing cols & beams

Elev 242 - Cleaning rust from cols & beams

Checked thickness told contractor to apply heavier coat

INSPECTOR: A. Calabrese DATE: 8-21-69 SHIFT: 9-4⁰⁰ REVIEWED BY:

EXPERIMENTAL 8-68

INSPECTOR'S DAILY NARRATIVE

CONTRACT NO.	CONTRACTOR	WEATHER
WTC 113-00	Mario & Di Bono	80°

Elev 310 - Spraying beams & cols

Elev 284 - Cleaning rust from cols & beams

Elev 274 - Fireproofing beams & cols

Elev 242 - Cleaning rust from cols & beams

Lost time - Temporary water - shut-off

INSPECTOR	DATE	SHIFT	REVIEWED BY
A. Kalaban	8-25-69	9-4	

EXPERIMENTAL 8-88

INSPECTOR'S DAILY NARRATIVE

CONTRACT NO.	CONTRACTOR	WEATHER
113.00	Mario & Di Bono	

Spraying 294 level Beams & Cols

Cleaning rust & overspray -242 & sub levels

D.M. Pacucci — INSPECTOR | 8/28/69 — DATE | SHIFT | A — REVIEWED BY

EXPERIMENTAL 8-88

INSPECTOR'S DAILY NARRATIVE

CONTRACT NO.	CONTRACTOR	WEATHER
113.00	Mario & Di Bono	

Spraying 242 level and 294 level.

Cleaning on sub-levels -"B"- Rust & Overspray

D.M. Pacucci — INSPECTOR | 8/27/69 — DATE | SHIFT | A — REVIEWED BY

EXPERIMENTAL 8-88

INSPECTOR'S DAILY NARRATIVE

CONTRACT NO.	CONTRACTOR	WEATHER
113.00	Mario & Di Bono	

Cleaning rust on 242 · Spraying 274 level and cleaning overspray

D.M. Pacucci — INSPECTOR | 8/26/69 — DATE | SHIFT | A — REVIEWED BY

EXPERIMENTAL 8-88

INSPECTOR'S DAILY NARRATIVE

CONTRACT NO.	CONTRACTOR	WEATHER
113.00	Mario & Di Bono	

Cleaning Rust- 2-3-7 -"B" & Sub levels

D.M. Pacucci — INSPECTOR | 8/29/69 — DATE | SHIFT | A — REVIEWED BY

EXPERIMENTAL 6-68

INSPECTOR'S DAILY NARRATIVE

CONTRACT NO.	CONTRACTOR	WEATHER
113.00	Mario & Di Bono	

Cleaning Rust - 3-4-5-7 - "A"

INSPECTOR: A.M. Pocucci DATE: 9/3/69 SHIFT: REVIEWED BY: A

EXPERIMENTAL 6-68

INSPECTOR'S DAILY NARRATIVE

CONTRACT NO.	CONTRACTOR	WEATHER
113.00	Mario & Di Bono	

Cleaning rust - on 2-3-4-7 - "A"

INSPECTOR: A.M. Pocucci DATE: 9/2/69 SHIFT: REVIEWED BY: A

EXPERIMENTAL 6-68

INSPECTOR'S DAILY NARRATIVE

Tower "A"

CONTRACT NO.	CONTRACTOR	WEATHER
WTC-113-00	Mario & D'Bono	80°

Elev 310 - 3rd floor - Fireproofing beams & cols

Elev - Floors - 4-5-6-7-8. Cleaning rust from cols & beams

INSPECTOR: A.J. Calabro DATE: 9-5-69 SHIFT: 9:00-11:00 REVIEWED BY: A

EXPERIMENTAL 6-68

INSPECTOR'S DAILY NARRATIVE

Tower A

CONTRACT NO.	CONTRACTOR	WEATHER
WTC 113-00	Mario & D'B	70°

Elev 310 - 3rd floor - Fireproofing beams & cols

Floors 4-5-6-7 Cleaning of steel from beams & cols.

M.T. & T.G. - Check for required thickness on beams & cols

INSPECTOR: A.J. Calabro DATE: 9-11-69 SHIFT: 9:00-11:00 REVIEWED BY: A

EXPERIMENTAL 8-68

INSPECTOR'S DAILY NARRATIVE

CONTRACT NO.	CONTRACTOR	WEATHER
113.00	DI BOND, MARIO E. PLASTERING COMPANY	SUNY.

FIREPROOFING

1 SPRAYING GUN ON LEVEL 294 SEALING OVERCOAT TOP COLUMNS NEAR ELEVATORS.

2nd SPRAYING GUN ON 4th FLOOR COLUMNS AND BEAMS WITHIN THE CORE

3rd SPRAYING GUN ON 9th FLOOR "Q" DECK BEAMS ON NORTH AND EAST SIDE

INSPECTOR	DATE	SHIFT	REVIEWED BY
[signature]	9-12-1969	8⁰⁰-4³⁰	

EXPERIMENTAL 8-68

INSPECTOR'S DAILY NARRATIVE

CONTRACT NO.	CONTRACTOR	WEATHER
WTC - 113-00	Mario + Di Bono	70's Rain

3-6 Floors - Fireproofing beams + cols

Elev 294 - Cleaning Welds + cols.

7-8-9-10 Cleaning dust from beams + cols

INSPECTOR	DATE	SHIFT	REVIEWED BY
A. J. Calabrese	9-8-69	8⁰⁰-4⁰⁰	A.

EXPERIMENTAL 8-68

INSPECTOR'S DAILY NARRATIVE

CONTRACT NO.	CONTRACTOR	WEATHER
WTC 113.00	MARIO & DI BONO	SUNNY & WARM

8:15 AM - 6" TEE IN WATER LINE AT EL294 J-5 BROKE STOPPING WATER flow INTO TOWER "A" SUPT for MARIO & DI BONO SENT ALL MEN HOME UNABLE TO SPRAY FIRE PROOFING WITHOUT WATER. PLUMBER ON DUTY CALLED FOR TEE. DISMANTLED ADJOINING PIPE. WILL HAVE WATER RUNNING BY 9:00 AM MONDAY 9/15/69.

N.Y.C FIRE DEPT DRILLING ON Job SITE 10:30 AM TO 11:30 AM.

INSPECTOR	DATE	SHIFT	REVIEWED BY
R.A. Vreeland	9/14/69	8-4:30	J.N.K.

EXPERIMENTAL 8-68

INSPECTOR'S DAILY NARRATIVE

CONTRACT NO.	CONTRACTOR	WEATHER
	Mario & Di Bono	

12 laborers - 4 plasterers - 4 machines

Spraying fireproofing on underside of 253 - two sprayers

Spraying 4th floor Columns

Spraying underside of 9th floor.

INSPECTOR	DATE	SHIFT	REVIEWED BY
A. M. Caracci	9/13/69		

B-88

INSPECTOR'S DAILY NARRATIVE

CONTRACT NO.	CONTRACTOR	WEATHER
113.00	DI BONO, MARIO E. PLASTERING COMPANY INC.	SUNY

FIREPROOFING

NO SPRAYING TODAY
CLEANING AND HANGING CONVASSES ON 10TH FLOOR, BOTH SIDES ON NORTH "Q" DECK AND ½ OF BOTH SIDES ON EAST AND WEST "Q" DECK

INSPECTOR: [signature] DATE: 9/16/1969 SHIFT: 8⁰⁰ TO 4³⁰ REVIEWED BY:

B-88

INSPECTOR'S DAILY NARRATIVE

CONTRACT NO.	CONTRACTOR	WEATHER
11300	DI BONO, MARIO E. PLASTERING COMPANY INC	SUNY

FIREPROOFING

2 SPRAYING GUNS ON 9TH FLOOR "Q" DECK BEAMS ON EAST SIDE WITH CORE BEAMS AND 2ND GUN ON SOUTH SIDE OF "Q" DECK.
1 SPRAYING GUN STARTED ON 10TH FLOOR AT N.E. CORNER AND WORKING TOWARDS N.W.

INSPECTOR: [signature] DATE: 9/15/1969 SHIFT: 8⁰⁰ TO 4³⁰ REVIEWED BY:

EXPERIMENTAL B-88

INSPECTOR'S DAILY NARRATIVE

CONTRACT NO.	CONTRACTOR	WEATHER
11300	DI BONO MARIO E. PLASTERING COMPANY	CLOUDY

FIREPROOFING

HAD 4 SPRAYING GUNS WORKING TODAY.
FINISHED SPRAYING NORTH SIDE, TOOK HANGING CONVASSES DOWN AND TRANSFERED TO 11TH FLOOR TO SOUTH SIDE WHERE HE STARTED SPRAYING AT 2⁰⁰ WITH ONE GUN AND HAD 2ND GUN AT 3⁰⁰ ON S.W CORNER OF 11TH FLOOR.
10TH FLOOR IS 95% FINISHED AND 11TH FLOOR HAS BEEN STARTED. SHOWED TO SUPERINTENDANT TONY BUARINO THAT UPPER PART OF HANGING ANGLES BEAMS WERE DEFICIENT. →

INSPECTOR: [signature] DATE: 9/18/1969 SHIFT: 8⁰⁰ TO 4³⁰ REVIEWED BY:

EXPERIMENTAL B-

INSPECTOR'S DAILY NARRATIVE

CONTRACT NO.	CONTRACTOR	WEATHER
113.00	DI BONO, MARIO E. PLASTERING COMPANY INC	SUNY

FIREPROOFING

CONTINUED HANGING CONVASSES ON EAST, WEST AND SOUTH SIDES OF "Q" DECK (COVERING EXTERIOR COLUMNS AN[D] CORE COLUMNS)
4 SPRAYING GUNS FINISHED 1ST LAYER ON 95% OF NORT[H] SIDE, 50% OF EAST SIDE, STARTED ON WEST SIDE AN[D] SOUTH SIDE.

INSPECTOR: [signature] DATE: 9/17/1969 SHIFT: 8⁰⁰ TO 4³⁰ REVIEWED BY:

EXPERIMENTAL 8-68

INSPECTOR'S DAILY NARRATIVE

CONTRACT NO.	CONTRACTOR	WEATHER
	Mario E. DiBono	

12 Laborers — 1 Supt. 1 Consultant Engr.
4 Sprayers (Plasterers) 1 Fore
4 Machines 1 Engr.

Spraying Underside of 253 - "A"
" 10th floor
" 11 "
" 12 "
Placing tarps around Core & Perimeter Col

INSPECTOR	DATE	SHIFT	REVIEWED BY
[illegible signature]	9/20/69		

8-68

INSPECTOR'S DAILY NARRATIVE

CONTRACT NO.	CONTRACTOR	WEATHER
11300	DI BONO MARIO E. PLASTERING COMPANY	SUNY

FIREPROOFING.
HAD 4 SPRAYING GUNS WORKING TODAY.
FINISHED TEMPORARELY SPRAYING 10th FLOOR & "Q" DECK ... BOTH SIDES OF 11th FLOOR "Q" DECKS COVERED BY HANGING CONVASSES AND TEMPORARELY FINISHED THE EAST SIDE EXCEPT N.E. CORNER; ABOUT 1/2 OF SOUTH; 3/4 ON WEST AND 1/2 OF NORTH
ON 12th FLOOR FINISHED COVERING EXTERIOR COLUMNS OF "Q" DECK ON SOUTH AND WEST SIDES.

INSPECTOR	DATE	SHIFT	REVIEWED BY
Fred [illegible]	9/19/1969	8 TO 4:30	

EXPERIMENTAL 8-68

INSPECTOR'S DAILY NARRATIVE

Tower A

CONTRACT NO.	CONTRACTOR	WEATHER
WTC 113·00	Mario & D'Bono	

Spraying interior cols 7-9-11-12 floors
Cleaning rust & overspray 7-9-11-12 floors

INSPECTOR	DATE	SHIFT	REVIEWED BY
A. J. Calabro	9-27-69	8-4:30	

EXPERIMENTAL 8-68

INSPECTOR'S DAILY NARRATIVE

Tower A

CONTRACT NO.	CONTRACTOR	WEATHER
WTC 113·00	Mario & D'Bono	

Cleaning rust from beams & cols 13 & 12 floors

Spraying 14th floor

INSPECTOR	DATE	SHIFT	REVIEWED BY
A. J. Calabro	9-26-69	8-4:30	

INSPECTOR'S DAILY NARRATIVE

CONTRACT NO.	CONTRACTOR	WEATHER
W.T.C. 11300	DI BONO MARIO E. PLASTERING COMPANY	SUNY

FIREPROOFING TOWER A.

HAD 4 SPRAYING GUNS WORKING TODAY.

1 GUN FINISHING 14th FLOOR. REMAINED 30% OF WEST SIDE.

3 GUNS FINISHED EAST AND SOUTH SIDES OF "A" DECK ON 15th FLOOR. SOME AREAS REMAINED COMPLETELY UNCOVERED.

HANGING CURTAINS REMAINED ON BOTH SIDES OF WEST SIDE ON 14th FLOOR; ALL AROUND "A" DECK ON BOTH SIDES ON 15th FLOOR AND ON OUTSIDE COLUMNS ALL AROUND "A" DECK ON 16th FLOOR.

WORK AS BEFORE NOT COMPLETE. UP TO 0" COVER

Fred [signature] — INSPECTOR | 9/29/1969 — DATE | 8 TO 4^30 — SHIFT | REVIEWED BY

EXPERIMENTAL 8-00

INSPECTOR'S DAILY NARRATIVE

Tower A

CONTRACT NO.	CONTRACTOR	WEATHER
WTC 113-00	Mario & D'Bono	

Fire-proofing 14-15-16th floors

Cleaning dust from steel 14+15th floors

A. J. Calicchio — INSPECTOR | 9-30-69 — DATE | 8:4:30 — SHIFT | REVIEWED BY

DAILY NARRATIVE

CONTRACT NO.	CONTRACTOR	WEATHER
WTC 113-00	Mario & D'Bono	

Spraying 7-9-13 floors

Cleaning dust & overspray 7-9-13 floors

A. J. Calicchio — INSPECTOR | 9-28-69 — DATE | 8:4:30 — SHIFT | REVIEWED BY

EXPERIMENTAL 8-00

INSPECTOR'S DAILY NARRATIVE

Tower A

CONTRACT NO.	CONTRACTOR	WEATHER
WTC 113-00	Mario & D'Bono	

Spraying 14+15th floors

Cleaning dust from beams & cols

A. J. Calicchio — INSPECTOR | 9-29-69 — DATE | 8:4:30 — SHIFT | REVIEWED BY

DAILY NARRATIVE

CONTRACT NO.	CONTRACTOR	WEATHER
WTC 113-00	Mario & D'Bono	

Fire-proofing 16 & 17th floors

Cleaning rust from Steel beams & Cols of 16 & 17th floors

A. J. Calabrese — INSPECTOR | 10-2-69 — DATE | 8-4:30 — SHIFT | REVIEWED BY

DAILY NARRATIVE

CONTRACT NO.	CONTRACTOR	WEATHER
WTC 113-00	Mario & D'Bono	

Fire-proofing 15-16-17 floors

Cleaning rust from Steel 15 & 16th floor

A. J. Calabrese — INSPECTOR | 10-1-69 — DATE | 8-4:30 — SHIFT | REVIEWED BY

INSPECTOR'S DAILY NARRATIVE

CONTRACT NO.	CONTRACTOR	WEATHER
113.00	Mario & D. Bono	

1 Supt. - 1 Fore - 6 fireproofers - 10 laborers
6 machines - 2 Engrs

Spraying core cols on 14-15-16 "A"
Spraying outside cols on 7 on North & South side of Building

Ciccaricci — INSPECTOR | 10/4/69 — DATE | SHIFT | REVIEWED BY

INSPECTOR'S DAILY NARRATIVE

Tower A

CONTRACT NO.	CONTRACTOR	WEATHER
WTC 113-00	Mario & D'Bono	

Fire-proofing 17-18th floors

Cleaning rust from Steel cols & beams 17th floor

A. J. Calabrese — INSPECTOR | 10-3-69 — DATE | 8-4:30 — SHIFT | REVIEWED BY

DAILY NARRATIVE

CONTRACT NO.	CONTRACTOR	WEATHER
WTC 113-00	Mario & Di Bono	

Fire-proofing 18th floor

General clean-up of oversprays

Cleaning dust from steel cols & beams

T.P.P. T. Torres - Cleaning & Thickness O.K.

INSPECTOR	DATE	SHIFT	REVIEWED BY
A. J. Calabrese	10-6-69	8:4:30	

DAILY NARRATIVE

CONTRACT NO.	CONTRACTOR	WEATHER
WTC 113-00	Mario & Di Bono	

Fire-proofing 13-14-15 floors Core beams & cols.

7th floor spraying exterior cols.

INSPECTOR	DATE	SHIFT	REVIEWED BY
A. J. Calabrese	10-4-69	8:4:30	

EXPERIMENTAL

INSPECTOR'S DAILY NARRATIVE

Torres A

CONTRACT NO.	CONTRACTOR	WEATHER
WTC 113-00	~~Dre-Hutchill~~ MARIO & DI BONO	

Cleaning dust & spraying 16-17-18-19 - floors

INSPECTOR	DATE	SHIFT	REVIEWED BY
A. J. Calabrese	10-9-69	8:4:30	

EXPERIMENTAL

INSPECTOR'S DAILY NARRATIVE

Torres A

CONTRACT NO.	CONTRACTOR	WEATHER
WTC 113-00	Mario & Di Bono	

Cleaning dust from cols. Spraying 16-17-18-19th floors

* Told A. Guarino to apply Cafco on to required thickness. Clean areas before leaving floors.

INSPECTOR	DATE	SHIFT	REVIEWED BY
A. J. Calabrese	10-8-69	8:4:30	

EXPERIMENTAL 8-68

INSPECTOR'S DAILY NARRATIVE

CONTRACT NO.	CONTRACTOR	WEATHER
TC 113-00	Mario & Di Bono	

Cleaning rust 18th floor

Spraying - plastering - Cleaning 17+18-19-20 floors

INSPECTOR: A. Halabian DATE: 10-10-69 SHIFT: 8-4:30 REVIEWED BY

EXPERIMENTAL 8-68

INSPECTOR'S DAILY NARRATIVE

CONTRACT NO.	CONTRACTOR	WEATHER
WTC 113-00	Mario & Di Bono	

Cleaning rust floor cols & beams 16-17 floors - Spraying & Cleaning 19 & 20 floors 16-17 floors

INSPECTOR: A. Halabian DATE: 10-8-69 SHIFT: 8-4:30 REVIEWED BY

EXPERIMENTAL 8-68

INSPECTOR'S DAILY NARRATIVE Tower B

CONTRACT NO.	CONTRACTOR	WEATHER
TC 113-00	Mario & Di Bono	

Cleaning - Spraying - protection 17 18-19-20 21 floors

INSPECTOR: A. Halabian DATE: 10/14/69 SHIFT: 8-4:30 REVIEWED BY

EXPERIMENTAL 8-68

INSPECTOR'S DAILY NARRATIVE

CONTRACT NO.	CONTRACTOR	WEATHER
113.00	Mario & Di Bono	

8 Plasterers - 14 laborers - 1 Fore - 1 Supt.
2 Hoist Engs. - 1 Const. Eng.

Spraying on 7th spandrel & beams
" " 16, 17, 18, 20
" overlay on 9th (Mach II)
" North outside cols - Mez.
Told A. Guarino to apply proper thickness and to clean up area

INSPECTOR: [signature] DATE: 10/11/69 SHIFT REVIEWED BY

EXPERIMENTAL 8-60

INSPECTOR'S DAILY NARRATIVE

CONTRACT NO.	CONTRACTOR	WEATHER
113.00	MARIO D BONO	CLEAR- WARM

4 sprayers they were working on the 2nd, 3rd, 7th, & 23rd floors
1-engineer
20 laborers - they were "cleaning up" from the 1st floor to the 23 floor. Before they left for the day, they swept the entire 310 deck.

K.K. O'Connell — INSPECTOR | 10/19/69 — DATE | 8-3:30 — SHIFT | REVIEWED BY

EXPERIMENTAL 8-60

INSPECTOR'S DAILY NARRATIVE

CONTRACT NO.	CONTRACTOR	WEATHER
WTC 113.00	MARIO & DIBONO	SUNNY - 60s

SPRAYED ASBESTOS FIREPROOFING ON COLUMNS & BEAM AT TOWER "A" ON 10TH, 11TH & 12TH FLOORS.

N.Y.C FIRE DEPT DRILLING AT JOB SITE.

R.A. Vreeland — INSPECTOR | 9/21/69 — DATE | 8-4:30 — SHIFT | REVIEWED BY

EXPERIMENTAL 8-60

INSPECTOR'S DAILY NARRATIVE

CONTRACT NO.	CONTRACTOR	WEATHER
113.00	Mario E Di Bono	

7 Plasterers - 16 laborers - 1 for - 2 hoist Engrs.
1 supt.

Spraying on 7th, 19, 21, 22, 23, Mezz
Unloaded truckload of plaster

Informed A. Guarino of proper thickness which should be sprayed
" " " Cleaning of elev. shafts must be concentrated on.

[illegible] — INSPECTOR | 10/18/69 — DATE | SHIFT | REVIEWED BY

EXPERIMENTAL 8-60

INSPECTOR'S DAILY NARRATIVE

CONTRACT NO.	CONTRACTOR	WEATHER
WTC 113.00	MARIO & DI BONO	SUNNY & WARM

SPRAY ON FIREPROOFING APPLIED TO COLUMNS & BEAMS ON THE FOLLOWING FLOORS IN TOWER "A" - 2, 7, 10, 11, 18, 19 & 20.
7 SPRAYERS WORKING TODAY. - 8 LABORERS WORKED ON CLEANUP IN AFTERNOON AT FLOORS SPRAYED AND EL. 310 AT NORTH, SOUTH & EAST, WEST SECTIONS SURROUNDING TOWER "A"

N.Y.C FIRE DEPT AT JOB SITE DRILLING

R.A. Vreeland — INSPECTOR | 10/12/69 — DATE | 8-4:30 — SHIFT | REVIEWED BY

EXPERIMENTAL 8-80

INSPECTOR'S DAILY NARRATIVE

CONTRACT NO.	CONTRACTOR	WEATHER
WTC 113·00	Mario + D'Bono	

Cleaning rust 19 + 20th floors

Spraying 18th floor

INSPECTOR	DATE	SHIFT	REVIEWED BY
G Kalaban	10·17·69		

EXPERIMENTAL 8-80

INSPECTOR'S DAILY NARRATIVE

CONTRACT NO.	CONTRACTOR	WEATHER
WTC 113·00	Mario + D'Bono	

Cleaning rust from cols + beams 19th fl

Spraying cleaning + protection 17 + 18-19

INSPECTOR	DATE	SHIFT	REVIEWED BY
G Kalaban	10·16·69	8·4·3	

EXPERIMENTAL 8-80

INSPECTOR'S DAILY NARRATIVE Tower A

CONTRACT NO.	CONTRACTOR	WEATHER
WTC 113·00	Mario + D'Bono	

Cleaning rust from cols + beams 20th fl.

Spraying. Cleaning-protection 18-19 floors

INSPECTOR	DATE	SHIFT	REVIEWED BY
G Kalaban	10·20·69	8·4·3	

INSPECTOR'S DAILY NARRATIVE

CONTRACT NO.	CONTRACTOR	WEATHER
113.00	Dic - Underhill	

Checking out reinforcing steel - sub 6" dia

Tishman cleaning floors - fine 13 days

[illegible] — INSPECTOR

1/1/69 — DATE

SHIFT

REVIEWED BY

INSPECTOR'S DAILY NARRATIVE

CONTRACT NO.	CONTRACTOR	WEATHER
113	MARIO D BONO	CLOUDY-WARM

6 sprayers	4 sprayers were using cafco
13 laborers	1 sprayer used 1 ouk coat
1 engineer	1 sprayer used zonolite
1 sup.	
1 foreman	2 sprayers were spraying "tree" col.
	east & west face of building
	3 sprayers worked on 10th fl.
	1 sprayer - 29 fl.

W. K. O'Connell — INSPECTOR
12/7/69 — DATE
8-4:30 — SHIFT
REVIEWED BY

INSPECTOR'S DAILY NARRATIVE

CONTRACT NO.	CONTRACTOR	WEATHER
WTC 113.0	Mario & DiBono	Cold 20's

1 Laborer Scraping Beams & Columns so drywall framing can be installed

INSPECTOR: Balduzzi DATE: 1/19/70 SHIFT: 0800-1630 REVIEWED BY:

INSPECTOR'S DAILY NARRATIVE

CONTRACT NO.	CONTRACTOR	WEATHER
WTC 113	Mario & DiBono	Cold 15°-20's

Contract (No Work) 1 Laborer Scraping Beams & Columns for drywall installation

INSPECTOR: Balduzzi DATE: 1/20/70 SHIFT: 0800-1630 REVIEWED BY:

INSPECTOR'S DAILY NARRATIVE

CONTRACT NO.	CONTRACTOR	WEATHER
WTC 113.00	Mario & DiBono	Rain Mild

10th Fl. - Ominous Wall Beams
1 Laborer Scraping Beams so Star Circle can install "J" Runners.

INSPECTOR: Balduzzi DATE: 1/3/70 SHIFT: 0800-1630 REVIEWED BY:

77-114

INSPECTOR'S DAILY NARRATIVE

EXPERIMENTAL B-68

CONTRACT NO.	CONTRACTOR	WEATHER
WTC 113.—	Mario & DiBono	Mild 40's

2 Mechanics 1 Hoisting Eng. 3 Laborers

29th Flr. 1 Mech. Spraying Trusses - (Top Header Ducts omitted.)

294 Level J-3 Area - 1 Mech. 2 Laborers Spraying Beams & Girders

Columns Members Re "Thickness"

INSPECTOR	DATE	SHIFT	REVIEWED BY
Balduzzi	2/11/70	0800-1130	

INSPECTOR'S DAILY NARRATIVE

EXPERIMENTAL B-68

CONTRACT NO.	CONTRACTOR	WEATHER
WTC 113.—	Mario & DiBono	Cold/30°

No Work —— No Water

INSPECTOR	DATE	SHIFT	REVIEWED BY
Balduzzi	2/6	8-4:30	

INSPECTOR'S DAILY NARRATIVE

EXPERIMENTAL B-68

CONTRACT NO.	CONTRACTOR	WEATHER
WTC 113	Mario & DiBono	30's Windy

29th Flr. Hung Canvas E/Side Bldg.

No Contract Work Completed.

INSPECTOR	DATE	SHIFT	REVIEWED BY
Balduzzi	2-13-70	8:00-4:30	

INSPECTOR'S DAILY NARRATIVE

EXPERIMENTAL B-68

CONTRACT NO.	CONTRACTOR	WEATHER
WTC 113.—	Mario & DiBono	30's

29th Flr. — 1 Man Spraying Columns

J-3/294 Elv. 1 Man Spraying 2 Cleaning Up.

310 Elv. 1 Hoist. Eng. 2 Lab. @ Machines —

INSPECTOR	DATE	SHIFT	REVIEWED BY
Balduzzi	2-12-70	800-430	

EXPERIMENTAL
INSPECTOR'S DAILY NARRATIVE

CONTRACT NO.	CONTRACTOR	WEATHER
WTC 113	Mario & Di Bono	Mild 30 – 40's

1. 294 Level – 2 mech 1 Lab. ~~[illegible]~~ [illegible] K-1 J-2 J-4 [illegible]
2. 30th FLR. – 2 Laborers installing canvas E/[illegible]
3. Lobby 310 – 1 [illegible] 3 Laborers
9 Men + [illegible] [illegible] [illegible] 450

[signature] INSPECTOR — 2/17/70 DATE — 8-4:30 SHIFT — REVIEWED BY

EXPERIMENTAL
INSPECTOR'S DAILY NARRATIVE

CONTRACT NO.	CONTRACTOR	WEATHER
WTC 113.0	Mario & Di Bono	Mild 30-40°

K-1 294 Level 2 [illegible] 1 Laborer [illegible]
[illegible]
Lobby – 1 [illegible] / 2 Laborers

[signature] INSPECTOR — 2/16/70 DATE — 8-4:30 SHIFT — REVIEWED BY

EXPERIMENTAL
INSPECTOR'S DAILY NARRATIVE

CONTRACT NO.	CONTRACTOR	WEATHER
WTC 113-	Mario & Di Bono	Cold 30's

No Work — Water Not Available

P. Balduzzi INSPECTOR — 2/20/70 DATE — 8-4:30 SHIFT — REVIEWED BY

EXPERIMENTAL
INSPECTOR'S DAILY NARRATIVE

CONTRACT NO.	CONTRACTOR	WEATHER
WTC 113	Mario & Di Bono	Mild 30°-40°

2 mech J area applying F.P. J-3 -J-4 Area.
3 Lab. " cleaning up
1 Eng Lobby Machine

[signature] INSPECTOR — 2-19-70 DATE — 8-4:30 SHIFT — REVIEWED BY

INSPECTOR'S DAILY NARRATIVE

CONTRACT NO.	CONTRACTOR	WEATHER
WTC. 113	Mario & Di Bono	Mild 30's

A.M. 1 man 29th FL. Columns/Core – Erection secured 12th

15th FL WTC 410

2 ea. " "

Discussed Overspray Protection with M/D Foreman, F.C. & F.M. (Tell) Perimeter Approval of Tarps, Interior Rooms every 3-5 FLRS was mutual conclusion.

Sat & Sun. Work will resume in March

29th FLR still incomplete.

INSPECTOR	DATE	SHIFT	REVIEWED BY
P. Balduzzi	2/27/70	8 – 4:30	

INSPECTOR'S DAILY NARRATIVE

CONTRACT NO.	CONTRACTOR	WEATHER
WTC 113.0	Mario & Di Bono	Mild 30+

J-4 2 operators No laborers

310 1 eng. 1 laborer

Observed J-4 Area Marked inadequate canvases used to protect exposed rebar – Rebar "Contaminated" by "spray on" Possible that Rebar should be cleaned prior to installation of concrete.

INSPECTOR	DATE	SHIFT	REVIEWED BY
Balduzzi	2-24-70	8am – 4:30	

INSPECTOR'S DAILY NARRATIVE

8-68

CONTRACT NO.	CONTRACTOR	WEATHER
WTC 113 —	Mario & DiBono	To 40's

A.M. - No work - Full crew on WTC #400

P.M. - 2 Lab Laborers Trimming Columns 29th Flr.
Non-Payment work.

INSPECTOR	DATE	SHIFT	REVIEWED BY
Balduzzi	3-3-70	8-4:30	

INSPECTOR'S DAILY NARRATIVE

8-68

CONTRACT NO.	CONTRACTOR	WEATHER
WTC 113.0	Mario & DiBono	Mild to 40's

No work No water

INSPECTOR	DATE	SHIFT	REVIEWED BY
Balduzzi	3/2/70	8-4:30	

INSPECTOR'S DAILY NARRATIVE

EXPERIMENTAL 8-68

CONTRACT NO.	CONTRACTOR	WEATHER
WTC 113.0	Mario & DiBono	Cold 30's

No Work - too Cold - TRCC did not turn on water

INSPECTOR	DATE	SHIFT	REVIEWED BY
Balduzzi	3/9/70	8-4:30	

INSPECTOR'S DAILY NARRATIVE

EXPERIMENTAL 8-68

CONTRACT NO.	CONTRACTOR	WEATHER
WTC 113	Mario & DiBono	Mild - 40's

Worked on WTC 400 only

INSPECTOR	DATE	SHIFT	REVIEWED BY
Balduzzi	3-6-70	8-4:30	

EXPERIMENTAL 8-88

INSPECTOR'S DAILY NARRATIVE

CONTRACT NO.	CONTRACTOR	WEATHER
WTC 113.00	Mario & DiBono	Mild 35-40s

Resumed Spray on Operation 30th Flr. truss area only — Advised foreman to apply material to P&T Duct (Return Duct)

Baldrazzi — INSPECTOR | 3/11/70 — DATE | 8-4:30 — SHIFT | REVIEWED BY

EXPERIMENTAL 8-88

INSPECTOR'S DAILY NARRATIVE

CONTRACT NO.	CONTRACTOR	WEATHER
WTC 113.00	Mario & DiBono	Cold - 30 & Breezy

6 Hours Waiting Time

No Water

Baldrazzi — INSPECTOR | 3/10/70 — DATE | 8-4:30 — SHIFT | REVIEWED BY

EXPERIMENTAL 8-88

INSPECTOR'S DAILY NARRATIVE

CONTRACT NO.	CONTRACTOR	WEATHER
WTC 113.0	Mario & DiBono	Fair 30-40s

Contractor Mixing Material per WTC 900,—

P.M. Check Flrs. 30 & above Delayed Because of Propane Fire J-6 Area. See Narrative 3-17-70

P. Baldrazzi — INSPECTOR | 3/16/70 — DATE | 8-4:30 — SHIFT | REVIEWED BY

EXPERIMENTAL 8-88

INSPECTOR'S DAILY NARRATIVE

CONTRACT NO.	CONTRACTOR	WEATHER
WTC 113—	Mario & DiBono	Cold - 30-40

No Work — Hold By TRCC — Site Circle

Must install J strip Prior to Spray-on Application

As directed by M. Gorstman, ~~Iron~~ Const.

Baldrazzi — INSPECTOR | 3/12/70 — DATE | 8-4:30 — SHIFT | REVIEWED BY

YIP-22

INSPECTOR'S DAILY NARRATIVE

CONTRACT NO.	CONTRACTOR	WEATHER
113 —	Mario & DiBono	Mild

3rd FLR. 2 SPRAYERS
2 LABORERS
1 FOREMAN
1st 1 LABORER
6 MEN TOTAL.

Informed Foreman that Area Has to Be Completely [illegible] ~~[illegible]~~ to Comply With City Requirements. Inspection At 1:30 & 2:00 Revealed No Heavy Usage [illegible]spray. Light Mist and FOG Escaping From Corner [illegible]. Heavy Particles Falling From Lower Levels (Cleaning work)

INSPECTOR: [illegible] DATE: 3/27/70 SHIFT: 8-8:30 REVIEWED BY:

INSPECTOR'S DAILY NARRATIVE

CONTRACT NO.	CONTRACTOR	WEATHER
WTC 113-00	Mario & DiBono	

Spraying & cleaning 17-18 floors
Cleaning [illegible] 15th floor

* Cautioned [illegible] about [illegible] pressure so the [illegible] material has good adhesion

INSPECTOR: [illegible] DATE: 10-15-68 SHIFT: [illegible] REVIEWED BY:

INSPECTOR'S DAILY NARRATIVE

CONTRACT NO.	CONTRACTOR	WEATHER
WTC 113	Mario & DiBono	Mild 40's

Applying material to truss area on 30th FLR. TRC [illegible] & [illegible] Stopped Operation 2:30 PM Because of "City" Order. ~~Spray~~ Over Spray Must Be Contained By Tarp Barrier—

INSPECTOR: [illegible] DATE: 3/25/70 SHIFT: 8-4:30 REVIEWED BY:

INSPECTOR'S DAILY NARRATIVE

CONTRACT NO.	CONTRACTOR	WEATHER
113.00	MARIO & DI BONO	CLEAR & COLD

TOWER "A"

5 SPRAYERS	7th fl. exterior face east and west side - sprayed
9 LABORERS	
2 ENGINEERS	9th fl. exterior face - south side sprayed
1 FORMAN	

INSPECTOR: N.K. O'Donnell DATE: 11/16/69 SHIFT: 8-4:30 REVIEWED BY:

INSPECTOR'S DAILY NARRATIVE

CONTRACT NO.	CONTRACTOR	WEATHER
WTC 113 -	Mario & DiBono	Cold 30-40° (Light Rain PM)

No Work 30th Flr & Above As Per Agreement with TRCC

INSPECTOR: [signature] DATE: 3/18/70 SHIFT: 8-4 30 REVIEWED BY:

INSPECTOR'S DAILY NARRATIVE

CONTRACT NO.	CONTRACTOR	WEATHER
WTC 113.0	Mario & DiBono	~~Fair 30-45~~

Field Trip — See Narrative 3/18/70

INSPECTOR: [signature] DATE: 3/17/70 SHIFT: Not on Job REVIEWED BY:

INSPECTOR'S DAILY NARRATIVE

CONTRACT NO.	CONTRACTOR	WEATHER
WTC 113 —	Mario & DiBono	Cold —

No Work Too Cold.

All Men Working on WTC 400

INSPECTOR: [signature] DATE: 3/31/70 SHIFT: 8-4 30 REVIEWED BY:

INSPECTOR'S DAILY NARRATIVE

CONTRACT NO.	CONTRACTOR	WEATHER
WTC 113	Mario & DiBono	Cold 8 AM 22°

No Application — Too Cold TRCC Did Not turn on Water

1 Foreman 3 Laborers Moving Compresses to lower Flr

INSPECTOR: [signature] DATE: 3/30/70 SHIFT: 8-4 30 REVIEWED BY:

YIP-22

EXPERIMENTAL 0-00

INSPECTOR'S DAILY NARRATIVE

CONTRACT NO.	CONTRACTOR	WEATHER
113	MARIO & DI BONA	

SPRAY ON INTERIOR
TRUSSES ON 31 & 32
FLOORS

4 MECH – 1 FOREMAN

13 LABORERS

INSPECTOR: [illegible] DATE: 4/[illegible]/70 SHIFT: 8-4:30 REVIEWED BY:

EXPERIMENTAL 0-00

INSPECTOR'S DAILY NARRATIVE

CONTRACT NO.	CONTRACTOR	WEATHER
113	Di Bono	Fair 45° wind

DiBono – Work force 1 Foreman, 4 Plasterers, 14 Laborers.
Spraying 32 floor trusses with Cafco C/F.

INSPECTOR: [illegible] DATE: 4-5-70 SHIFT: 1 REVIEWED BY:

EXPERIMENTAL 0-00

INSPECTOR'S DAILY NARRATIVE

CONTRACT NO.	CONTRACTOR	WEATHER
WTC 113	MARIO & DiBono	Mild

33rd FL – 1 MAN PROTECTING TRUSSES
2 MEN HANGING TARPS
2 MEN PLACING HOSES & SPRAYING (PLASTERS)
32nd FL 3 PLASTERS – SPRAYING & MOVING EQUIPMENT.
31st FL 3 LABORERS CLEANING UP.
NEW FOREMAN – JAMES CALLENDRELLA REACTS to GOOD SITUATION Re: 1. CANVAS PROTECTION 2./ SPRAYING HIGHER Out of NECESSARY HARNESS.
STILL CIRCLES LACK of "J" INSTALLATION HOLDING UP COLUMN COATING.
All LABORERS CLEANING UP 10th FL.

INSPECTOR: Baldizzar[illegible] DATE: 4/6/70 SHIFT: 8-4:30 REVIEWED BY:

EXPERIMENTAL 0-00

INSPECTOR'S DAILY NARRATIVE

CONTRACT NO.	CONTRACTOR	WEATHER
113	DiBona	FAIR

1 Foreman
4 Mechanics
12 Laborers

41st Floor Spraying Beams & Trusses
35th Floor " Trusses
35th Floor Hanging Tarps.

INSPECTOR: [illegible] DATE: 4-11-70 SHIFT: DAY REVIEWED BY:

INSPECTOR'S DAILY NARRATIVE

CONTRACT NO.	CONTRACTOR	WEATHER
113	DeBona	Fair

Floors at which Cofers Sprayed or Taum above 28
Hood 75% Comp. 28-29-30-31-32-33-34-35-36
50% Complete 37-41
Tarps up ready to Spray 38-39
No Tarps on 42

W. Schleif — INSPECTOR | 4-25-70 — DATE | Day — SHIFT | REVIEWED BY

INSPECTOR'S DAILY NARRATIVE

CONTRACT NO.	CONTRACTOR	WEATHER
113	DiBona	Rain

Sparklets Fed Cascade Re 41 fl Cofers on Bed Beam -
Steamfitters complained that Cofers is going down Back
as it sticks - [illegible] to contact DiBona to remove
same - Sparklets Fed 4 PM - was unable to contact
them - he will try tomorrow AM.

W. Schleif — INSPECTOR | 4-23-70 — DATE | Day — SHIFT | REVIEWED BY

INSPECTOR'S DAILY NARRATIVE

CONTRACT NO.	CONTRACTOR	WEATHER
113	De Bona	Fair

De Bona received [illegible] material today. (Samples of both [illegible] old [illegible] in Inspection office) he intends to start spraying [illegible] as soon as he receives more material which should be Thursday or Friday 4-30 - 5-1.

W Schleif — INSPECTOR | 4-29-70 — DATE | Day — SHIFT | REVIEWED BY

INSPECTOR'S DAILY NARRATIVE

CONTRACT NO.	CONTRACTOR	WEATHER
113	De Bona	Fair

41 [illegible] scraping Bottom Flange of Beams
40 [illegible] Spraying Box Joints

Statement from De Bona office that they will start spraying Green [illegible] on Monday 5-25-70

W Schleif — INSPECTOR | 5-21-70 — DATE | Day — SHIFT | REVIEWED BY

INSPECTOR'S DAILY NARRATIVE

8-60

CONTRACT NO.	CONTRACTOR	WEATHER
113	De Bona	Fair

De Bona Started to spray Trusses on 37 floor & 38 floor. Hanging Tarps on 41 to Complete same

W Schley — INSPECTOR | 5-5-70 — DATE | Day — SHIFT | REVIEWED BY

INSPECTOR'S DAILY NARRATIVE

8-60

CONTRACT NO.	CONTRACTOR	WEATHER
113	De Bona	Fair

Started on 41 floor 1PM Spraying Bottom of Flange Beam Nos. 8 completed over Roof of Sub Station. They started to put together scaffold that belong to Collins and they took it away from them. De Bona Will have to procure other ones to continue. The plumbers are wanting a scaffold now at the South East Elevation 41-

W Schley — INSPECTOR | 5-12-70 — DATE | Day — SHIFT | REVIEWED BY

EXPERIMENTAL 8-60

INSPECTOR'S DAILY NARRATIVE

CONTRACT NO.	CONTRACTOR	WEATHER
113	De Bona	Fair

When I came in to cover Stan Cecil last PM I found that De Bona sprayed on 41 floor at Stat. again he did not have proper protection to prevent the Cafco from going out of Building & down Elm Street. This was brought to my attention by Vance Markel - TRCC. In spite of Vance continuously Paging his Jimmy of De Bona never returned call when he finally did he never showed up at Tishman Trailer - Something has got to be done with this contractor. Admin.

W Schley — INSPECTOR | 5-9-70 — DATE | Day — SHIFT | REVIEWED BY

EXPERIMENTAL 8-60

INSPECTOR'S DAILY NARRATIVE

CONTRACT NO.	CONTRACTOR	WEATHER
113	De Bona	Fair

1 Man Spraying Beams 38 floor.
Scaffold still set on 41 to spray Bottom flanges but no activity.

De Bona changed again and now found the Color of cement shall be Blue

Floors are loaded with overspray of Cafco - No one is cleaning - Vance

W Schley — INSPECTOR | 5-22-70 — DATE | Day — SHIFT | REVIEWED BY

INSPECTOR'S DAILY NARRATIVE

CONTRACT NO.	CONTRACTOR	WEATHER
113	Di Bona	Cloudy

Spraying Truss on 39 fl.
Started to scrape 41 floor again at 2 PM - brought Frank Tartaroello up on floor to see condition - We then went to the foreman of DiBona & heard the same story of not enough men on job - they had four hours. Frank then said he was going to speak to Tom DiBona for more men & scaffold attempt to complete job by Saturday.

W. Schleif — INSPECTOR | 5-14-70 — DATE | Day — SHIFT | REVIEWED BY

INSPECTOR'S DAILY NARRATIVE

CONTRACT NO.	CONTRACTOR	WEATHER
113	Di Bona	Fair

Scraping Bottom of Floor pan on 41 floor 2 men Complete as of this date 17 on NW Elevation & 12½ on SW.

Spraying Truss on 39 fl.

W. Schleif — INSPECTOR | 5-15-70 — DATE | Day — SHIFT | REVIEWED BY

EXPERIMENTAL
INSPECTOR'S DAILY NARRATIVE

CONTRACT NO.	CONTRACTOR	WEATHER
113	Di Bona	Fair

No Work on this Contract as per Jimmy of DiBona

W. Schleif — INSPECTOR | 5-11-70 — DATE | Day — SHIFT | REVIEWED BY

EXPERIMENTAL
INSPECTOR'S DAILY NARRATIVE

CONTRACT NO.	CONTRACTOR	WEATHER
113	Di Bona	Rain in am - fair PM

~~No Work on this~~ Spraying Truss on 39 fl.

No Work on 41st floor as far as scraping bottom flange

W. Schleif — INSPECTOR | 5-13-70 — DATE | Day — SHIFT | REVIEWED BY

DAILY NARRATIVE

CONTRACT NO.	CONTRACTOR	WEATHER
113	Di Bona	Fair

Spraying Deck underside & Beam 6th floor
Cleaning 6th floor

[illegible] — 5-29-70 — Day

INSPECTOR	DATE	SHIFT	REVIEWED BY
[illegible]	5-29-70	Day	

INSPECTOR'S DAILY NARRATIVE

CONTRACT NO.	CONTRACTOR	WEATHER
113	WTC	Clear -60°

8 Plasterers spray-on in the following locations -
(6 men) (1) 31 - 34 floors: Corridors & El. lobbies, El shafts
(2-men) (2) Also 2-84 [illegible] - spray on -

INSPECTOR	DATE	SHIFT	REVIEWED BY
[illegible]	5/30/70	8-4:30	

EXPERIMENTAL INSPECTOR'S DAILY NARRATIVE

CONTRACT NO.	CONTRACTOR	WEATHER
113	Di Bona	Cloudy-Rain

Spraying Caps on Trusses 39 floor 1 man
2 men cleaning floor 41 fl.

Bottom flange of Beam Steel not Completed
41st floor.

INSPECTOR	DATE	SHIFT	REVIEWED BY
[illegible]	5-19-70	DAY	

EXPERIMENTAL INSPECTOR'S DAILY NARRATIVE

CONTRACT NO.	CONTRACTOR	WEATHER
113	Di Bona	Fair

Spraying overcoat on 11 floor

INSPECTOR	DATE	SHIFT	REVIEWED BY
[illegible]	5-28-70	DAY	

INSPECTOR'S DAILY NARRATIVE

CONTRACT NO.	CONTRACTOR	WEATHER
113	Mario DiBona	Fair

Spraying 39 floor
Patching 2&4 Level } A Tower
Cleaning 39 floor

Note Color of overcoat shall be Green

Contract worked till 12 noon - only -

Bott of Beams on 41 fl still knock for Second - DiBona is going to start tomorrow Agreement ???

INSPECTOR: W Schley DATE: 5-20-70 SHIFT: Day REVIEWED BY:

INSPECTOR'S DAILY NARRATIVE

CONTRACT NO.	CONTRACTOR	WEATHER
113	DiBona	Fair

DiBona still spraying on 41 floor Bottom of Beams I spoke to Fred Connole T.R. again He called Tony Bonomo of DiBona and he stated that there was no agreement between Burt Weinstein & DiBona. and he will continue to spray Bottom. Fred then called Burt Weinstein & told him of conversation including the fact that Sand Cantin will not do anything until Beams are scraped clean. They want DiBona to seal carefully & scrape. Burt told Fred that if Sand Cantin wants to hang pipe they would scrape - & Burt Weinstein would tell them to do so.

INSPECTOR: W Schley DATE: 5-7-70 SHIFT: DAY REVIEWED BY:

INSPECTOR'S DAILY NARRATIVE

CONTRACT NO.	CONTRACTOR	WEATHER
113	Di Bona	Cloudy 70°

3 Plasterers 5 laborers - spraying fire proofing 38 & 39 floor shafts and overhead ceiling lobby ceiling

INSPECTOR: [illegible] DATE: 6/27/70 SHIFT: 1 REVIEWED BY:

INSPECTOR'S DAILY NARRATIVE

CONTRACT NO.	CONTRACTOR	WEATHER
113	DiBona	Fair

Spraying Bar Joists 45 fl -

Jimmy Ebler Eng. complained that some one is cutting Pipes on Tarps & Removing Wash [illegible] his paper spray is going out of Bldg & he is receiving reports -

INSPECTOR: W Schley DATE: 6-29-70 SHIFT: DAY REVIEWED BY:

8-88

INSPECTOR'S DAILY NARRATIVE

CONTRACT NO.	CONTRACTOR	WEATHER
113	Mario De Bono	Fair

Bar Joists 48
Welding 12-13
Spraying [illegible] 12

[illegible signature] — INSPECTOR | 6-19-70 — DATE | Day — SHIFT | — REVIEWED BY

8-88

INSPECTOR'S DAILY NARRATIVE

CONTRACT NO.	CONTRACTOR	WEATHER
113	De Bono	Cloudy - Rain

Spraying Bar Joist 43 Floor
Spraying Slab 11 Floor

[illegible signature] — INSPECTOR | 6-4-70 — DATE | Day — SHIFT | — REVIEWED BY

EXPERIMENTAL
8-88

INSPECTOR'S DAILY NARRATIVE

CONTRACT NO.	CONTRACTOR	WEATHER
113	De Bono	Fair

No Work on this Contract today - (Spraying)
Preparing 43 ? floor for Spraying Bar Joists
It is my knowledge that De Bono has OK
to spray only to 41 floor. [illegible]

[illegible signature] — INSPECTOR | 6-2-70 — DATE | Day — SHIFT | — REVIEWED BY

EXPERIMENTAL
8-88

INSPECTOR'S DAILY NARRATIVE

CONTRACT NO.	CONTRACTOR	WEATHER
113	De Bono	Rain Cloudy

Spraying 43 floor - Bar Joists
Note: New Cafe 32 floor top of 6th floor & from 36 up
old Cafe Balance

[illegible signature] — INSPECTOR | 6-5-70 — DATE | Day — SHIFT | — REVIEWED BY

XIP-22

INSPECTOR'S DAILY NARRATIVE

6-60

CONTRACT NO.	CONTRACTOR	WEATHER
113	DiBona	Rain 65°

DiBona had 4 plasterers, 8 laborers, 1 engineer and 1 foreman working on spraying fireproofing on columns 32 & 33 floors

Someone cut one water hose part way through which caused quite a bit of water to run over the 32 floor and down the [illegible] of center stairs before the water was turned off. Also three electric control wire were cut by person unknown

INSPECTOR: [illegible] DATE: 6-6-70 SHIFT: 1 REVIEWED BY:

INSPECTOR'S DAILY NARRATIVE

EXPERIMENTAL 6-60

CONTRACT NO.	CONTRACTOR	WEATHER
113	DiBona	Fair

No Work on this Contract Today

INSPECTOR: [illegible] DATE: 6-1-70 SHIFT: DAY REVIEWED BY:

INSPECTOR'S DAILY NARRATIVE

EXPERIMENTAL 6-60

CONTRACT NO.	CONTRACTOR	WEATHER
113	DiBona	Fair

Spraying [illegible] past 43 floor
Patching on 10 floor
Spraying overcoat on Decking 10 floor

INSPECTOR: W. Schleif DATE: 6-9-70 SHIFT: DAY REVIEWED BY:

EXPERIMENTAL 8-66

INSPECTOR'S DAILY NARRATIVE

CONTRACT NO.	CONTRACTOR	WEATHER
113	De Bona	Fair

Spraying Box Joint 44 floor
Cleaning floor 43
Spraying Concrete 11
Filling Voids columns 11 fl.

[illegible signature] INSPECTOR — 6-11-78 DATE — Day SHIFT — REVIEWED BY

EXPERIMENTAL 8-66 XIP-22

INSPECTOR'S DAILY NARRATIVE

CONTRACT NO.	CONTRACTOR	WEATHER
113	De Bona	Fair

The following columns have been closed with Con. Box that must be removed in order for Di Bona can Complete the Cafco spray in Voids.
10 floor - #1008 - 1007 - 1006 - 1004 - 1003 - 1002 - 1001
11 floor #501 - 502 503 504 505 506 507 508
1008 - 1007 - 1006 - 1004 - 1003 - 1002 - 1001

[illegible signature] INSPECTOR — 6-11-78 DATE — Day SHIFT — REVIEWED BY

EXPERIMENTAL 8-66

INSPECTOR'S DAILY NARRATIVE

CONTRACT NO.	CONTRACTOR	WEATHER
113	De Bona	Fair

Spraying 10 floor - filling Voids - PT cells - also Spraying overcoat on Decking.
Spraying Box Joint 43-44

[illegible signature] INSPECTOR — 6-8-78 DATE — Day SHIFT — REVIEWED BY

EXPERIMENTAL 8-66

INSPECTOR'S DAILY NARRATIVE

CONTRACT NO.	CONTRACTOR	WEATHER
113	De Bona	Fair

Spraying Cafco 10 fl. filling in Voids.
Spraying overcoat on Decking
Spraying Cafco Box Joint 43 fl.

Note on 35 floor Star Circle closing in Shaft 10-11 I told Johnny Blue Eye to opening. His statement was that He would side the top of Con to Complete his Work

[illegible signature] INSPECTOR — 6-10-78 DATE — Day SHIFT — REVIEWED BY

EXPERIMENTAL 8-68

INSPECTOR'S DAILY NARRATIVE

CONTRACT NO.	CONTRACTOR	WEATHER
113	Di Bona	Fair

Spraying Cofers on 44 fl. Box Joint
Spraying 6th floor Level
Patching 12 floor
Overcoat Spray 12 floor

INSPECTOR	DATE	SHIFT	REVIEWED BY
[illegible signature]	6-15-70	DAY	

EXPERIMENTAL 8-68 YIP-22

INSPECTOR'S DAILY NARRATIVE

CONTRACT NO.	CONTRACTOR	WEATHER
113	Di Bona	Fair

Spraying Cofers Box Joint 44
Patching 12
Spraying Overspray 12

INSPECTOR	DATE	SHIFT	REVIEWED BY
[illegible signature]	6-12-70	DAY	

EXPERIMENTAL 8-68

INSPECTOR'S DAILY NARRATIVE

CONTRACT NO.	CONTRACTOR	WEATHER
Wtc. 113.00	MARIO DI BONO	FAIR 80°

SPRAYING INTERIOR COLUMNS AND BEAMS ON:
32nd FL - 1 SPRAYER - 1 LABORER
33rd FL - " "
35th FL - " "
36th FL - " "
38th FL - 1 ENG WORKING ON 3 MACHINES.

INSPECTOR	DATE	SHIFT	REVIEWED BY
[illegible signature]	6/13/1970	1	

EXPERIMENTAL 8-68

INSPECTOR'S DAILY NARRATIVE

CONTRACT NO.	CONTRACTOR	WEATHER
113	Di Bona	Fair

Patching 12
Spraying overcoat 12
Box Joint 44
Undercoating 6 floor

INSPECTOR	DATE	SHIFT	REVIEWED BY
[illegible signature]	6-16-70	DAY	

G-66

INSPECTOR'S DAILY NARRATIVE

CONTRACT NO.	CONTRACTOR	WEATHER
113	De Bono	Fair 70°

Completing the spraying fireproofing on shafts at 30, 32, 33 34 35 floors and starting 38 & 39 floors. 4 plasterers, 5 laborers

INSPECTOR: [signature] DATE: 6-20-70 SHIFT: 1 REVIEWED BY:

YIP-22

G-66

INSPECTOR'S DAILY NARRATIVE

CONTRACT NO.	CONTRACTOR	WEATHER
113	Mario De Bono	Fair

Spraying Cols 6th floor
Patching N-16 fl.

INSPECTOR: [signature] DATE: 6-23-70 SHIFT: Day REVIEWED BY:

EXPERIMENTAL G-66

INSPECTOR'S DAILY NARRATIVE

CONTRACT NO.	CONTRACTOR	WEATHER
113	De Bono	Fair

Spraying Bar Joist 44-45
Patching 11-13
Spraying emergency 12

INSPECTOR: [signature] DATE: 6-17-70 SHIFT: Day REVIEWED BY:

EXPERIMENTAL G-66

INSPECTOR'S DAILY NARRATIVE

CONTRACT NO.	CONTRACTOR	WEATHER
113	De Bono	Rain - Fair

44-45 Spraying Bar Joist
11-13 floor Patching
12 Spraying emergency

INSPECTOR: [signature] DATE: 6-18-70 SHIFT: Day REVIEWED BY:

8-66

INSPECTOR'S DAILY NARRATIVE

CONTRACT NO.	CONTRACTOR	WEATHER
113	Di Bona	Rain

Overspray 6
Patching 21-22

[illegible] — INSPECTOR | 6-26-70 — DATE | Day — SHIFT | REVIEWED BY

EXPERIMENTAL
8-66

INSPECTOR'S DAILY NARRATIVE

CONTRACT NO.	CONTRACTOR	WEATHER
113	Di Bona	Fair

Box Joint 45
Overspray 6-13
Patching 19-20

[illegible] — INSPECTOR | 6-25-70 — DATE | Day — SHIFT | REVIEWED BY

8-66

INSPECTOR'S DAILY NARRATIVE

CONTRACT NO.	CONTRACTOR	WEATHER
113	Mario Di Bona	Fair

Spraying Box joints 45
Overspray 13

[illegible] — INSPECTOR | 6-30-70 — DATE | Day — SHIFT | REVIEWED BY

EXPERIMENTAL
8-66

INSPECTOR'S DAILY NARRATIVE

CONTRACT NO.	CONTRACTOR	WEATHER
113	Mario Di Bona	Fair

Patching 17-18
Overspray 13
Marked overspray 6

[illegible] — INSPECTOR | 6-24-70 — DATE | Day — SHIFT | REVIEWED BY

YIP-22

EXPERIMENTAL
8-68

INSPECTOR'S DAILY NARRATIVE

CONTRACT NO.	CONTRACTOR	WEATHER
113	Marie de Bona	Fair

No work on this Contract today

[illegible] INSPECTOR — 7-3-70 DATE — Day SHIFT — REVIEWED BY

EXPERIMENTAL
8-68

INSPECTOR'S DAILY NARRATIVE

CONTRACT NO.	CONTRACTOR	WEATHER
113	Marie de Bona	Rain

Bar joint 45
Sweeping 14
Patching 2.5

[illegible] INSPECTOR — 7-2-70 DATE — Day SHIFT — REVIEWED BY

EXPERIMENTAL
8-68

INSPECTOR'S DAILY NARRATIVE

CONTRACT NO.	CONTRACTOR	WEATHER
113	Marie De Bona	Fair

Spreading Bar joint 45
Sweeping 13-14

[illegible] INSPECTOR — 7-1-70 DATE — Day SHIFT — REVIEWED BY

EXPERIMENTAL
8-68

INSPECTOR'S DAILY NARRATIVE

CONTRACT NO.	CONTRACTOR	WEATHER
113	Marie de Bona	Fair

Sweeping 14 ft.

[illegible] INSPECTOR — 7-6-70 DATE — Day SHIFT — REVIEWED BY

YIP-22

INSPECTOR'S DAILY NARRATIVE

CONTRACT NO.	CONTRACTOR	WEATHER
113	Mario & Di Bono Co	

Tower "B"

As per change # 730,003 add #2 — this compute trusses prepared on the 10 Fl. — 3 men.

Draping the 7 Fl —

INSPECTOR	DATE	SHIFT	REVIEWED BY
R A O'Hare	7/9/70	8/4 30	

EXPERIMENTAL
8-68

INSPECTOR'S DAILY NARRATIVE

CONTRACT NO.	CONTRACTOR	WEATHER
113	Mario F. Di Bona	Fair

Drumming 14'

W. Schleif — 7-7-70 — Day

INSPECTOR — DATE — SHIFT — REVIEWED BY

8-68

YIP-22 INSPECTOR'S DAILY NARRATIVE

CONTRACT NO.	CONTRACTOR	WEATHER
113	Mario F. Di Bona	

Tower "B"
two men finishing up 10 ft TEL-6
Wrapping 7ft & Protection.

R A O'Hara — 7/10/70 — 8/4:30

INSPECTOR — DATE — SHIFT — REVIEWED BY

EXPERIMENTAL
8-68

INSPECTOR'S DAILY NARRATIVE

CONTRACT NO.	CONTRACTOR	WEATHER
113	Mario F. Di Bona	

Tower "B"

Wrapping 7 ft - West & North side.

Wrapping interior of 10 ft mock up

this work (spray) should start Friday.

R A O'Hara — 7/8/70 — 8/4:30

INSPECTOR — DATE — SHIFT — REVIEWED BY

EXPERIMENTAL
8-68

INSPECTOR'S DAILY NARRATIVE

CONTRACT NO.	CONTRACTOR	WEATHER
113	Mario F. Di Bona	Fair

Drumming 14 ft.

W. Schleif — 7-8-70 — Day

INSPECTOR — DATE — SHIFT — REVIEWED BY

B-88

INSPECTOR'S DAILY NARRATIVE

CONTRACT NO.	CONTRACTOR	WEATHER
113	Marie & Di Bona	

Tour B
7th Ave.

Spray on —
1 Clean-up
1 on machine
2 plasterers (TRUSS & Q deck.)
(This work started Sat with the same crew. Di Bona did not know until 4 PM that he was working - No coverage)

C. A. O'Hara — 7/13/70 — 8-4 PM

INSPECTOR — DATE — SHIFT — REVIEWED BY

XIP-22

B-88

INSPECTOR'S DAILY NARRATIVE

CONTRACT NO.	CONTRACTOR	WEATHER
113	Marie & Di Bona	Fair

No Work on this Contract

N. Schultz — 7-14-70 — Day

INSPECTOR — DATE — SHIFT — REVIEWED BY

EXPERIMENTAL

B-88

INSPECTOR'S DAILY NARRATIVE

CONTRACT NO.	CONTRACTOR	WEATHER
113	Marie & Di Bona	Fair

Overspray 15 ft.

N. Schultz — 7-9-70 — Day

INSPECTOR — DATE — SHIFT — REVIEWED BY

EXPERIMENTAL

B-88

INSPECTOR'S DAILY NARRATIVE

CONTRACT NO.	CONTRACTOR	WEATHER
113	Marie & Di Bona	Rain

Overspray 14 ft.

N. Schultz — 7-10-70 — Day

INSPECTOR — DATE — SHIFT — REVIEWED BY

YIP-22

INSPECTOR'S DAILY NARRATIVE

CONTRACT NO.	CONTRACTOR	WEATHER
113	Mario & Di Bona	

Tower "B"

1. Visitors from Tel-Co & Mr Fegan inspected Mock up on 10 E, requested another sample taken with less material & less tamping.

2. Four ~~plasterers~~ laborers, two plasterers on 7 E - 13 on Q deck etc on West side - spray-on

INSPECTOR	DATE	SHIFT	REVIEWED BY
R.A. O'Hara	7/15/70	8/4:30	

INSPECTOR'S DAILY NARRATIVE

CONTRACT NO.	CONTRACTOR	WEATHER
113	Mario & De Bona	Cloudy

No Work on this Contract today

INSPECTOR	DATE	SHIFT	REVIEWED BY
W Kelley	7-15-70	Day	

INSPECTOR'S DAILY NARRATIVE

CONTRACT NO.	CONTRACTOR	WEATHER
113	Mario & De Bona	Fair

No Work on this Contract

INSPECTOR	DATE	SHIFT	REVIEWED BY
W Kelley	7-13-70	Day	

INSPECTOR'S DAILY NARRATIVE

CONTRACT NO.	CONTRACTOR	WEATHER
113	Mario & Di Bona	" "

Tower B

Spray On, MER "Q" deck 1½" application, etc, West side two Plasterers, four laborers

INSPECTOR	DATE	SHIFT	REVIEWED BY
R.A. O'Hara	7/14/70	8/4:30	

INSPECTOR'S DAILY NARRATIVE

CONTRACT NO.	CONTRACTOR	WEATHER
113	Mario & DiBona	Fair

Draping 16 fl

Inspector: [illegible] — Date: 7-17-70 — Shift: Day — Reviewed by:

XIP-22 INSPECTOR'S DAILY NARRATIVE

CONTRACT NO.	CONTRACTOR	WEATHER
113	Mario & Di Bona	

Tower "B"

Two Plasters & 4 Labores on Spray on 7 Fl or 9 Fl area

Cautioned Di Bona about spraying underside of flanges, with overloads.

Inspector: L.A. O'Hara — Date: 7/17/70 — Shift: 8/4:30 — Reviewed by:

INSPECTOR'S DAILY NARRATIVE

CONTRACT NO.	CONTRACTOR	WEATHER
113	Mario & Di Bona	

Tower "B"

7 Floor
Two plasters spray on truss, etc
Four labours on clean up and machine.
Two Labours on draping.

10 Fl.
Two Plasters on Tel.-Co Area on mock-up (using vermiculite for tighter compaction)

Inspector: L.A. O'Hara — Date: 7/16/70 — Shift: 8/4:30 — Reviewed by:

INSPECTOR'S DAILY NARRATIVE

CONTRACT NO.	CONTRACTOR	WEATHER
113	Mario & DiBona	Fair

Draping 14-15-16

Inspector: [illegible] — Date: 7-16-70 — Shift: Day — Reviewed by:

XIP-22

INSPECTOR'S DAILY NARRATIVE

CONTRACT NO.	CONTRACTOR	WEATHER
113	Mario & Di Bona	

Tower B
7 Fl.
Two Plasterers Spray on
Four Laborers to Clean
up & Machine

INSPECTOR: [illegible] DATE: 7/21/70 SHIFT: 8/4 30 REVIEWED BY:

INSPECTOR'S DAILY NARRATIVE

CONTRACT NO.	CONTRACTOR	WEATHER
113	Mario & Di Bona	Fair

Nothing on this Contract Tower A

INSPECTOR: [illegible] DATE: 7-21-70 SHIFT: Day REVIEWED BY:

INSPECTOR'S DAILY NARRATIVE

CONTRACT NO.	CONTRACTOR	WEATHER
Safety		Fair

Fire Dept came on Tower Sunday 7-19-70 in answer to alarm by Police Dept. Went to 71 fl & checked - no fire however fire extinguisher had been turned on by someone & completely emptied - 1st Battalion plus fire Boat answered call 11 45 AM -

INSPECTOR: [illegible] DATE: 7-19-70 SHIFT: Day REVIEWED BY:

INSPECTOR'S DAILY NARRATIVE

CONTRACT NO.	CONTRACTOR	WEATHER
113	Mario & Di Bona	Fair

Murphy 16 floor.

INSPECTOR: [illegible] DATE: 7-20-70 SHIFT: Day REVIEWED BY:

YIP-22

INSPECTOR'S DAILY NARRATIVE

CONTRACT NO.	CONTRACTOR	WEATHER
113	Mario & DeBona	Fair

No work on this contract today Tower A

INSPECTOR: [illegible] DATE: 7-23-70 SHIFT: Day REVIEWED BY:

INSPECTOR'S DAILY NARRATIVE

CONTRACT NO.	CONTRACTOR	WEATHER
113	Mario & DeBona	

Tower B - 7 Fl.
Two Plasterers - spray on
Three on Clean Up & Machine sl.
wall.

INSPECTOR: [illegible] DATE: 7/23/70 SHIFT: 8/4:30 REVIEWED BY:

INSPECTOR'S DAILY NARRATIVE

CONTRACT NO.	CONTRACTOR	WEATHER
113	Mario & DeBona	

Tower "B"
7 Fl.
Two Plasterers - Spray on
Three Labors Clean Up &
Machine 310 wall

INSPECTOR: [illegible] DATE: 7/22/70 SHIFT: 8/4:30 REVIEWED BY:

INSPECTOR'S DAILY NARRATIVE

CONTRACT NO.	CONTRACTOR	WEATHER
113	Mario & DeBona	Fair

No work on this contract Tower A

INSPECTOR: [illegible] DATE: 7-22-70 SHIFT: Day REVIEWED BY:

XIP-22

INSPECTOR'S DAILY NARRATIVE

CONTRACT NO.	CONTRACTOR	WEATHER
113	Mario & Di Bona	Fair

Spraying Box Joints 46

Overspray 26

INSPECTOR	DATE	SHIFT	REVIEWED BY
[illegible signature]	7-22-70	Day	

INSPECTOR'S DAILY NARRATIVE

CONTRACT NO.	CONTRACTOR	WEATHER
113	Mario & Di Bona	Fair

Box Joints 46 ft

Overspray 17 ft

INSPECTOR	DATE	SHIFT	REVIEWED BY
[illegible signature]	7-23-70	Day	

EXPERIMENTAL

INSPECTOR'S DAILY NARRATIVE

CONTRACT NO.	CONTRACTOR	WEATHER
113	Mario & Di Bona	

Tower "B"
7 Floor.

1-plaster spray on (overspray) — areas left. Call for spray on and overspray

3 laborers — Clean up & Machine
310 [illegible]

INSPECTOR	DATE	SHIFT	REVIEWED BY
[illegible signature]	7/24/70	8-4:30	

EXPERIMENTAL

INSPECTOR'S DAILY NARRATIVE

CONTRACT NO.	CONTRACTOR	WEATHER
113	Mario & Di Bona	Fair

Overspray 17 floor.

INSPECTOR	DATE	SHIFT	REVIEWED BY
[illegible signature]	7-24-70	Day	

EXPERIMENTAL 8-88

INSPECTOR'S DAILY NARRATIVE

CONTRACT NO.	CONTRACTOR	WEATHER
113	Mario & Di Bona	Fair

Spraying Box Joints 46
on fireproofing 17

INSPECTOR	DATE	SHIFT	REVIEWED BY
[illegible signature]	7-28-70	Day	

YIP-22 **DAILY NARRATIVE**

CONTRACT NO.	CONTRACTOR	WEATHER
113	Mario & Di Bona	Fair

Spraying Box joint 46 ft
on fireproofing 17 ft

INSPECTOR	DATE	SHIFT	REVIEWED BY
[illegible signature]	7-20-70	Day	

EXPERIMENTAL 8-88

INSPECTOR'S DAILY NARRATIVE

CONTRACT NO.	CONTRACTOR	WEATHER
113	Mario & Di Bona	

Tower B
7 E

1 Plaster spray on core
three on clean up
One on machine 3:10-

INSPECTOR	DATE	SHIFT	REVIEWED BY
[illegible signature]	7/27/70	8-4:30	

EXPERIMENTAL 8-88

INSPECTOR'S DAILY NARRATIVE

CONTRACT NO.	CONTRACTOR	WEATHER
113	Mario & Di Bona	

Tower 'B'
7 E.

1 Plaster on over-spray lost [illegible]
2 on clean up

INSPECTOR	DATE	SHIFT	REVIEWED BY
[illegible signature]	7/29/70	8-4:30	

XIP-28

EXPERIMENTAL G-66

INSPECTOR'S DAILY NARRATIVE

CONTRACT NO.	CONTRACTOR	WEATHER
113	Mario & Di Bona	

Tower "B"
7 Floor

Two laborers on Clean up

98% on spray-on Complete
Con not complete
until Mec-[illegible]
completes stripping

INSPECTOR	DATE	SHIFT	REVIEWED BY
[signature]	8/31/70	8/4:30	

EXPERIMENTAL G-66

INSPECTOR'S DAILY NARRATIVE

CONTRACT NO.	CONTRACTOR	WEATHER
113	Mario & Di Bona	

Tower B
7 Fl

1 Plaster on Spray on east side
3 Laborers

INSPECTOR	DATE	SHIFT	REVIEWED BY
[signature]	7/30/70	8/4:30	

EXPERIMENTAL G-66

INSPECTOR'S DAILY NARRATIVE

CONTRACT NO.	CONTRACTOR	WEATHER
113	Mario & Di Bona	

Tower B

One plaster-over-spray
east side
Three laborers - Clean up
& Machine 310 level

INSPECTOR	DATE	SHIFT	REVIEWED BY
[signature]	7/28/70	8/4:30	

EXPERIMENTAL G-66

INSPECTOR'S DAILY NARRATIVE

CONTRACT NO.	CONTRACTOR	WEATHER
113	Mario & Di Bona	Sun

Spraying Box Joists 46 ft
Overspray 18 ft.

INSPECTOR	DATE	SHIFT	REVIEWED BY
[signature]	7-31-70	Day	

YIP-22

INSPECTOR'S DAILY NARRATIVE

CONTRACT NO.	CONTRACTOR	WEATHER
113	Mario & Di Bona	

Tower "B"
7E

2 men on clean up areas not striped by the Underhill only 98%

INSPECTOR	DATE	SHIFT	REVIEWED BY
[illegible signature]	8/4/70	Day	

INSPECTOR'S DAILY NARRATIVE

CONTRACT NO.	CONTRACTOR	WEATHER
113	Mario & Di Bona	

Tower A

2 men 19 ft overspray

INSPECTOR	DATE	SHIFT	REVIEWED BY
[illegible signature]	8/5/70	Day	

INSPECTOR'S DAILY NARRATIVE

CONTRACT NO.	CONTRACTOR	WEATHER
113	Mario & Di Bona	

Tower B

2 men on clean-up 7E
Floor not finished due to no striping by Mic. (M&D 98%)

INSPECTOR	DATE	SHIFT	REVIEWED BY
[illegible signature]	8/5/70	Day	

INSPECTOR'S DAILY NARRATIVE

CONTRACT NO.	CONTRACTOR	WEATHER
113	Mario & Di Bona	

Tower A
19 ft

2 Plasters on overspray

INSPECTOR	DATE	SHIFT	REVIEWED BY
[illegible signature]	8/4/70	Day	

YIP-22

INSPECTOR'S DAILY NARRATIVE (Experimental 8-60)

CONTRACT NO.	CONTRACTOR	WEATHER
113	Mario & Di Bona	1 of 2

Tower A

As per letter dated 8/27/70 — Re: fireproof steel in case area work. Found that as follows

60 ft	1 Plaster	1 Labor	1 on Machine
59 ft	"	"	
58 ft	"	"	
57 ft	"	"	
50 ft	"	"	
49 ft	"	"	
48 ft		"	1 on Machine

INSPECTOR — DATE 8/29/70 — SHIFT — REVIEWED BY

INSPECTOR'S DAILY NARRATIVE (Experimental 8-60)

CONTRACT NO.	CONTRACTOR	WEATHER
113	Mario & Di Bona	

Tower A

2 Plasters 19 ft overspray

INSPECTOR R H O'Hara — DATE 8/3/70 — SHIFT Day — REVIEWED BY

INSPECTOR'S DAILY NARRATIVE (Experimental 8-60)

CONTRACT NO.	CONTRACTOR	WEATHER
113	Mario & Di Bona	

Tower B

2 men Clean up 7 ft MER

INSPECTOR R H O'Hara — DATE 8/5/70 — SHIFT Day — REVIEWED BY

INSPECTOR'S DAILY NARRATIVE (Experimental 8-60)

CONTRACT NO.	CONTRACTOR	WEATHER
113	Mario & Di Bona	2 of 2

47 ft	1 Plaster	1 Labor	
40 "	"	"	
39 "	"	"	
38 "		"	1 man on Ma

1 Foreman 10 plasters
13 Labors

Contractor worked till 6 PM. Went over work & called out where thickness was not as required. Corrective measures to be taken. Foreman

INSPECTOR R H O'Hara — DATE 8/29/70 — SHIFT Day — REVIEWED BY

YIP-22

INSPECTOR'S DAILY NARRATIVE

EXPERIMENTAL 8-68

CONTRACT NO.	CONTRACTOR	WEATHER
113	Mario & DiBona	

Tower B

2 Men on Clean up 7 Fl.

Inspector: [signature] Date: 8/7/70 Shift: Day Reviewed by:

INSPECTOR'S DAILY NARRATIVE

EXPERIMENTAL 8-68

CONTRACT NO.	CONTRACTOR	WEATHER
113	Mario & DiBona	

Tower A

2 plasterers on 46 Fl. Cafco. spray on

Inspector: [signature] Date: 8/7/70 Shift: day Reviewed by:

INSPECTOR'S DAILY NARRATIVE

EXPERIMENTAL 8-68

CONTRACT NO.	CONTRACTOR	WEATHER
113	Mario & DiBona	

Tower A

Inst. Cafco on 46 Fl. - 2 plasterers.

Inspector: [signature] Date: 8/6/70 Shift: Day Reviewed by:

INSPECTOR'S DAILY NARRATIVE

EXPERIMENTAL 8-68

CONTRACT NO.	CONTRACTOR	WEATHER
113	Mario & DiBona	

Tower B

2 laborers on Clean up 7 Fl.

Inst. material for 310 scaffold for lobby spray-on

Inspector: [signature] Date: 8/6/70 Shift: Day Reviewed by:

YIP-22

EXPERIMENTAL 8-60

INSPECTOR'S DAILY NARRATIVE

CONTRACT NO. 113 | CONTRACTOR Mario & Di Bona | WEATHER

Tower A

2 plasterers start spray on 48 Floor bar joists

INSPECTOR: [illegible] | DATE 8/11/70 | SHIFT day | REVIEWED BY

EXPERIMENTAL 8-60

INSPECTOR'S DAILY NARRATIVE

CONTRACT NO. 113 | CONTRACTOR Mario & Di Bona | WEATHER

Tower B

2 on Clean up 7 Fl

INSPECTOR: [illegible] | DATE 8/11/70 | SHIFT day | REVIEWED BY

EXPERIMENTAL 8-60

INSPECTOR'S DAILY NARRATIVE

CONTRACT NO. 113 | CONTRACTOR Mario & Di Bona | WEATHER

Tower B

No Work on Clean up in A17

2 Men on Clean up B17

INSPECTOR: [illegible] | DATE 8/10/70 | SHIFT day | REVIEWED BY

EXPERIMENTAL 8-60

INSPECTOR'S DAILY NARRATIVE

CONTRACT NO. 113 | CONTRACTOR Mario & Di Bona | WEATHER

Tower A

Preparation for 47 Fl

Start Spray (Cafco)

8/11

INSPECTOR: [illegible] | DATE 8/10 | SHIFT day | REVIEWED BY

XIP-22

EXPERIMENTAL 8-68

INSPECTOR'S DAILY NARRATIVE

CONTRACT NO.	CONTRACTOR	WEATHER
113	Maris & Di Bona	

Tower B

Two laborers on clean up TH

INSPECTOR: [signature] DATE: 8/13/70 SHIFT: Day REVIEWED BY:

EXPERIMENTAL 8-68

INSPECTOR'S DAILY NARRATIVE

CONTRACT NO.	CONTRACTOR	WEATHER
113	Maris & Di Bona	

Tower A

2 plasterers - 2 laborers

Spray bar joints

Worked till 6 PM

INSPECTOR: [signature] DATE: 8/13/70 SHIFT: Day REVIEWED BY:

EXPERIMENTAL 8-68

INSPECTOR'S DAILY NARRATIVE

CONTRACT NO.	CONTRACTOR	WEATHER
113	Maris & Di Bona	

Tower B

2 on clean up TH

INSPECTOR: [signature] DATE: 8/12/70 SHIFT: Day REVIEWED BY:

EXPERIMENTAL 8-68

INSPECTOR'S DAILY NARRATIVE

CONTRACT NO.	CONTRACTOR	WEATHER
113	Maris & Di Bona	

Tower A

2 Plasterers on 49 floor on bar joints

INSPECTOR: [signature] DATE: 8/12/70 SHIFT: Day REVIEWED BY:

KIP-22

EXPERIMENTAL

INSPECTOR'S DAILY NARRATIVE

CONTRACT NO.	CONTRACTOR	WEATHER
113	Maris & DiBona	

Tower A

2 plasters 2 laborers working on bar joists 49 ft.

INSPECTOR: [illegible] DATE: 8/17/70 SHIFT: Day REVIEWED BY:

EXPERIMENTAL

INSPECTOR'S DAILY NARRATIVE

CONTRACT NO.	CONTRACTOR	WEATHER
113	Maris & DiBona	Fair/Rain

No work on this contract today

INSPECTOR: [illegible] DATE: 8-17-70 SHIFT: DAY REVIEWED BY:

EXPERIMENTAL

INSPECTOR'S DAILY NARRATIVE

CONTRACT NO.	CONTRACTOR	WEATHER
113	Maris & DiBona	

Tower A

2 plasterers on 49 ft bar joists

INSPECTOR: [illegible] DATE: 8/17/70 SHIFT: Day REVIEWED BY:

EXPERIMENTAL

INSPECTOR'S DAILY NARRATIVE

CONTRACT NO.	CONTRACTOR	WEATHER
113	Maris & DiBona	

Tower B

2 men on clean up TRMS

INSPECTOR: [illegible] DATE: 8/17/70 SHIFT: Day REVIEWED BY:

XIP-22

INSPECTOR'S DAILY NARRATIVE

CONTRACT NO.	CONTRACTOR	WEATHER
113	Mario F. DeBona	Fair

Spraying Box Joints 47 Fl.
Setting up Traps.

[illegible] — INSPECTOR; 8-20-70 — DATE; DAY — SHIFT; REVIEWED BY

INSPECTOR'S DAILY NARRATIVE

CONTRACT NO.	CONTRACTOR	WEATHER
113	Mario F. DeBona	Fair

Spraying Box Joints 42 Fl.

[illegible] — INSPECTOR; 8-21-70 — DATE; DAY — SHIFT; REVIEWED BY

EXPERIMENTAL

INSPECTOR'S DAILY NARRATIVE

CONTRACT NO.	CONTRACTOR	WEATHER
113	Mario F. DeBona	Fair

Spraying Box Joints 48 floor

[illegible] — INSPECTOR; 8-18-70 — DATE; DAY — SHIFT; REVIEWED BY

EXPERIMENTAL

INSPECTOR'S DAILY NARRATIVE

CONTRACT NO.	CONTRACTOR	WEATHER
113	Mario F. DeBona	Fair

Box Joints Spraying 48 floor

[illegible] — INSPECTOR; 8-19-70 — DATE; DAY — SHIFT; REVIEWED BY

XIP-22

EXPERIMENTAL
8-68

INSPECTOR'S DAILY NARRATIVE

CONTRACT NO.	CONTRACTOR	WEATHER
113	Mari & De Bona	Fair

2 Men spraying Bar Joints 59 floor

W Kehlay — 8-26-70 — Day

INSPECTOR — DATE — SHIFT — REVIEWED BY

EXPERIMENTAL
8-68

INSPECTOR'S DAILY NARRATIVE

CONTRACT NO.	CONTRACTOR	WEATHER
113	Mari & De Bona	Fair

Spraying Bar Joints
60 - 47 - 50 - 58
2 men

W Kehlay — 8-27-70 — Day

INSPECTOR — DATE — SHIFT — REVIEWED BY

EXPERIMENTAL
8-68

INSPECTOR'S DAILY NARRATIVE

CONTRACT NO.	CONTRACTOR	WEATHER
113	De Bona	Fair

Spraying Bar Joints 47-59
6 Men

W Kehlay — 8-24-70 — Day

INSPECTOR — DATE — SHIFT — REVIEWED BY

EXPERIMENTAL
8-68

INSPECTOR'S DAILY NARRATIVE

CONTRACT NO.	CONTRACTOR	WEATHER
113	Mari & De Bona	Fair

No Work Today on this Contract

W Kehlay — 8-25-70 — Day

INSPECTOR — DATE — SHIFT — REVIEWED BY

YIP-22

EXPERIMENTAL 0-60

INSPECTOR'S DAILY NARRATIVE

CONTRACT NO.	CONTRACTOR	WEATHER
113	Marino & McKeon	10 p 2

Tower A

As per letter dated 8/27/70 – fireproof steel in [illegible] area – work [illegible] [illegible] as follows – (Architect [illegible] [illegible] [illegible] [illegible])

60 fl 2 Plasterers – 1 laborer + 1 man [illegible]

59 fl 1 Plasterer – 1 labor

58 fl " "

57 fl " "

50 fl " "

49 fl " "

48 fl " " + 1 man on machine

INSPECTOR ____ 8/30/70 SHIFT ____ REVIEWED BY ____

EXPERIMENTAL 0-60

INSPECTOR'S DAILY NARRATIVE

CONTRACT NO.	CONTRACTOR	WEATHER
113	Marino & McKeon	

Tower A

12 Plasterers, 9 Laborers, 1 Foreman

Spray bar joists on 56, 57, 58, 60 & 61

INSPECTOR [signature] DATE 8/31/70 SHIFT Day REVIEWED BY ____

EXPERIMENTAL 0-60

INSPECTOR'S DAILY NARRATIVE

CONTRACT NO.	CONTRACTOR	WEATHER
113	Marino & DeBona	Fair

Spraying Bar Joints Tower A

60 – 50 – 58

6 Men

INSPECTOR [signature] DATE 8-28-70 SHIFT DAY REVIEWED BY ____

EXPERIMENTAL 0-60

INSPECTOR'S DAILY NARRATIVE

CONTRACT NO.	CONTRACTOR	WEATHER
113	Marino & McKeon	70/2

Tower "A"

47 fl 1 Plasterer – 1 labor

41 fl " "

40 fl " "

38 fl 1 man on mach

1 Foreman – 11 Plasterers – 13 Laborers

Work for both days in areas is 80% complete this includes the work in shafts 6-7 & 50 [illegible] left [illegible] [illegible] on shaft 50. Will go over area & [illegible] report Monday with contractor

INSPECTOR [signature] DATE 8/30/70 SHIFT [illegible] REVIEWED BY [illegible]

INSPECTOR'S DAILY NARRATIVE

CONTRACT NO. 113 | CONTRACTOR Mario & Di Bono | WEATHER

Tower B

Spray beams (1/2") path
26-24 level
1 Plaster, 2 Laborers
1 Machine

INSPECTOR [illegible signature] DATE 9/9/70 SHIFT Day REVIEWED BY

INSPECTOR'S DAILY NARRATIVE

CONTRACT NO. 113 | CONTRACTOR MARIO & DI BONO | WEATHER CLOUDY

TOWER "A"

ONE FOREMAN, FOUR PLASTERERS AND FIVE LABORERS. SPRAY-ON FIRE-PROOFING ON CORE STEEL ON FLOORS 40, 41, 51 AND 52. MACHINE LOCATED ON 39TH FLOOR. THIS WORK PERFORMED ON AN OVERTIME BASIS. CONTRACTOR WORKED UNTIL 7:00 P.M.

INSPECTOR Lou [illegible] DATE 9/3/70 SHIFT 4:00-7:00 REVIEWED BY

EXPERIMENTAL

INSPECTOR'S DAILY NARRATIVE

CONTRACT NO. 113 | CONTRACTOR Mario & Di Bono | WEATHER

Tower A

Cafes spray core steel on per letter [illegible] 8/27/70

51 two plasterers 1 Labor
38 One " 1 " (1 Man on machine)
41 One " 1 "
56 One 1 "

(Also Worked in Areas also 6-41-59 & lobby)

INSPECTOR [illegible signature] DATE 9/2/70 SHIFT 4:30 8:30 REVIEWED BY

EXPERIMENTAL

INSPECTOR'S DAILY NARRATIVE

CONTRACT NO. 113 | CONTRACTOR Mario & Di Bono | WEATHER

Tower "A"

Three Plasterers, Two Laborers on core [illegible] on 51-52-56-57

Informed [illegible] [illegible] core steel on [illegible] [illegible] [illegible] [illegible] [illegible] [illegible] (2:30 [illegible])

INSPECTOR [illegible signature] DATE 9/4/70 SHIFT Day REVIEWED BY

0-00 DAILY NARRATIVE

CONTRACT NO.	CONTRACTOR	WEATHER
	Mario & Di Bono	

Started spraying underside of 264 beams tower "B" SE corner.

[signature] — INSPECTOR; 9/2/70 — DATE; SHIFT; REVIEWED BY

EXPERIMENTAL 0-00 INSPECTOR'S DAILY NARRATIVE

CONTRACT NO.	CONTRACTOR	WEATHER
113	Mario & Di Bono	

Tower "A"

1. 14 Laborers; 7 plasterers on 51 to 57 floors — doing bar joists and cell steel on the floors.
2. Overspray on 22 fl.
3. Spray on 264 truss (Track)

[signature] — INSPECTOR; 9/2/70 — DATE; Day — SHIFT; REVIEWED BY

EXPERIMENTAL 0-00 INSPECTOR'S DAILY NARRATIVE

CONTRACT NO.	CONTRACTOR	WEATHER
113	Mario & Di Bono	

Tower "A"

12 plasterers, nine laborers, 1 foreman spray bar joists on 50-57-58-60 & 61 floors

[signature] — INSPECTOR; 9/1/70 — DATE; Day — SHIFT; REVIEWED BY

INSPECTOR'S DAILY NARRATIVE

CONTRACT NO.	CONTRACTOR	WEATHER
113	Mario F. DeBona	Cloudy / Rain

Spraying Bar joist. 55-61-62-63

INSPECTOR: W Schlief DATE: 9-18-70 SHIFT: Day REVIEWED BY:

INSPECTOR'S DAILY NARRATIVE

CONTRACT NO.	CONTRACTOR	WEATHER
110 - TRCC	Star Circle & TRCC	

113 - Bank "A" - Tower A

[illegible] coat strip Car 28 9

Caulking

TRCC forces on Clean up and [illegible] work overtime

Mario & [illegible] Bond [illegible] have to apply [illegible] 2 [illegible] while they are [illegible]

INSPECTOR: [illegible] DATE: 9/16/70 SHIFT: Day REVIEWED BY:

INSPECTOR'S DAILY NARRATIVE

CONTRACT NO.	CONTRACTOR	WEATHER
113	Mario F DeBona	Fair

Spraying Core Columns. 43-44-45-46-47

6 Plaster
8 Lab
2 Foreman
1 Eng
} 17

3 Lab in Elev Bank A Clean up.

8AM - 5:30 PM

INSPECTOR: W Schlief DATE: 9-20-70 SHIFT: Day REVIEWED BY:

INSPECTOR'S DAILY NARRATIVE

CONTRACT NO.	CONTRACTOR	WEATHER
113	Mario F DeBona	Fair

Spraying Core Columns. 43-44-45-46
47-48-62

12 Plaster
13 Lab
1 Plaster Foreman
2 Labor Foreman
1 Eng.
} 29 men

Spraying Bank A - 1 Plaster, 1 Lab. } 2 31 Tot

INSPECTOR: W Schlief DATE: 9-19-70 SHIFT: Day REVIEWED BY:

INSPECTOR'S DAILY NARRATIVE

CONTRACT NO.	CONTRACTOR	WEATHER
113	Mario & DeBono	Fair

No work on the Contract Today

INSPECTOR	DATE	SHIFT	REVIEWED BY
[signature]	9-22-70	Day	

INSPECTOR'S DAILY NARRATIVE

CONTRACT NO.	CONTRACTOR	WEATHER
113	Mario & DeBono	Fair

Spraying Box Joist 63-55-54
2 Men - 9-4

Spraying Core Column 55-56 Tower extra
2 Men
4 Lab
1 Foreman
} 2 hrs. 4 to 6 PM

INSPECTOR	DATE	SHIFT	REVIEWED BY
[signature]	9-21-70	Day	

EXPERIMENTAL

INSPECTOR'S DAILY NARRATIVE

CONTRACT NO.	CONTRACTOR	WEATHER
113	Mario & DeBono	

Tower B
Telephone Area
11 Ft.
Started this date: As per sample
on 10 Ft
Two Plasters One Labor

INSPECTOR	DATE	SHIFT	REVIEWED BY
[signature]	9/19/70	Day	

EXPERIMENTAL

INSPECTOR'S DAILY NARRATIVE

CONTRACT NO.	CONTRACTOR	WEATHER
113	Mario & DeBono	

Tower B
11 Ft - Tel-Co Area
Two Plasters & Four Labors
applying spray on area in
accordance with 5th Supplemental
agreement. (S.W. Corner)
Note: Notified Tel-Co Mr. Moromend the
above areas are available for
inspection

INSPECTOR	DATE	SHIFT	REVIEWED BY
[signature]	9/18/70	Day	

INSPECTOR'S DAILY NARRATIVE

CONTRACT NO.	CONTRACTOR	WEATHER
113	MARIO & DI BONO	PARTLY SUNNY

TOWER 'A'

ONE FOREMAN, FIVE PLASTERS AND SIX LABORERS. SPRAY-ON FIRE-PROOFING ON THE 52ND, 53RD AND 56TH FLOORS OF CORE STEEL. CONTRACTOR WORKED FROM 5PM. TO 8PM ON AN OVERTIME BASIS.

INSPECTOR: [signature] DATE: 9/8/70 SHIFT: 4PM-8PM REVIEWED BY:

INSPECTOR'S DAILY NARRATIVE

CONTRACT NO.	CONTRACTOR	WEATHER
113	Mario & Di Bono	

Tower "B"

Spray on in the path area 242 & 250 Il.

2 plasterers, 3 laborers

INSPECTOR: [signature] DATE: 9/9/70 SHIFT: Day REVIEWED BY:

EXPERIMENTAL

INSPECTOR'S DAILY NARRATIVE

CONTRACT NO.	CONTRACTOR	WEATHER
113	Mario & Di Bono	

Tower A

9 Plasterers, 8 laborers
51-52-56 bar joists.

INSPECTOR: [signature] DATE: 9/8/70 SHIFT: Reg REVIEWED BY:

EXPERIMENTAL

INSPECTOR'S DAILY NARRATIVE

CONTRACT NO.	CONTRACTOR	WEATHER
113	Mario & Di Bono	

Tower B

Spray on N.W. Path area
2 plasterers 1 laborer

INSPECTOR: [signature] DATE: 9/8/70 SHIFT: Day REVIEWED BY:

DAILY NARRATIVE

CONTRACT NO.	CONTRACTOR	WEATHER
113	Mario F. DeBono	Fair

Spraying Box Joints 53-55 floors

W. Schleif — 9-11-70 — Day

INSPECTOR — DATE — SHIFT — REVIEWED BY

EXPERIMENTAL

INSPECTOR'S DAILY NARRATIVE

CONTRACT NO.	CONTRACTOR	WEATHER
113	Mario F. DeBono	Rain

Spraying Box Joints 52 53 - 55 - 56

7 men

W. Schleif — 9-9-70 — Day

INSPECTOR — DATE — SHIFT — REVIEWED BY

DAILY NARRATIVE

CONTRACT NO.	CONTRACTOR	WEATHER
113	Mario F. DeBono	Fair

Spraying Core Column Tower A

Floor	Mech	Lab	
54th floor	1	1	
53 "	1	1	Machine men
52 "	1	1	1 - 48
45 "	1	1	2 - 38
44 "	1	1	2 Helpers
43 "	0	1	
42 "	1	1	Total
41 "	1	1	20 men
Bank A	1	1	2 Helpers

W. Schleif — 9-13-70 — Day

INSPECTOR — DATE — SHIFT — REVIEWED BY

EXPERIMENTAL

INSPECTOR'S DAILY NARRATIVE

CONTRACT NO.	CONTRACTOR	WEATHER
113	Mario F. DeBono	Fair

Spraying Core Columns.

Floor	Mech		Labor	
54 floor	2 Mech		1 Labor	
53 "	2	"	1	"
45 "	1	"	1	"
44 "	1	"	1	"
43 "	1	"	1	"
42 "	1	"	1	"
41 "	1	"	1	"
40 "	1	"	1	"
Bank A	1	"	2	"

2 Machine men 38
1 " " 48
2 Helpers

Total 24 men
2 Helpers

W. Schleif — 9-12-70 — Day

INSPECTOR — DATE — SHIFT — REVIEWED BY

8-68 DAILY NARRATIVE

CONTRACT NO.	CONTRACTOR	WEATHER
113	Mario & DiBono	Fair

Spraying Bar Joists 54-55 floor
6 Men Plasterers
12 Labor Clean ups

[signature] — 9-14-70 — DAY

INSPECTOR — DATE — SHIFT — REVIEWED BY

8-68 INSPECTOR'S DAILY NARRATIVE

CONTRACT NO.	CONTRACTOR	WEATHER
113	Mario & DiBono	

Tower B
Two Laborers - setting up 9th fire spray [illegible]

[signature] — 9/14/70 — Day

INSPECTOR — DATE — SHIFT — REVIEWED BY

EXPERIMENTAL 8-68 INSPECTOR'S DAILY NARRATIVE

CONTRACT NO.	CONTRACTOR	WEATHER
113	Mario & DiBono	Cloudy Rain

Spraying Bar Joists 53-55
Spraying Core Columns 53-55 on Connections T&M

[signature] — 9-10-70 — DAY

INSPECTOR — DATE — SHIFT — REVIEWED BY

EXPERIMENTAL 8-68 INSPECTOR'S DAILY NARRATIVE

CONTRACT NO.	CONTRACTOR	WEATHER
113	Mario & DiBono	Fair

Spraying Core Columns 54-55 fl.
6 Sprayers
2 Mortar Men
4 Labor
2 Supers
T&M

[signature] — 9-14-70 — 4-6:30 PM

INSPECTOR — DATE — SHIFT — REVIEWED BY

DAILY NARRATIVE

CONTRACT NO.	CONTRACTOR	WEATHER
113	Mario F. DeBona	Fair

Spraying Box Joint 55-61-62-63

INSPECTOR: [signature] DATE: 9-17-70 SHIFT: Day REVIEWED BY:

INSPECTOR'S DAILY NARRATIVE

CONTRACT NO.	CONTRACTOR	WEATHER
113	Mario & Di Bona	

Tower A
Bank A

Three labors in AM; two in afternoon, not enough to complete then one shaft as informed Mr. Tartamella. TKCC forces coming in 12 midnight to do patching and should go on cleaning. Will inform Joe Darbone of walls dept to do

INSPECTOR: [signature] DATE: 9/20/70 SHIFT: Day REVIEWED BY:

EXPERIMENTAL

INSPECTOR'S DAILY NARRATIVE

CONTRACT NO.	CONTRACTOR	WEATHER
113	Mario F. DeBona	Cloudy / Rain

Spraying Box Joint 54-55- 1/2 Day-
Work Stop due to Man being Killed in Tower B.

INSPECTOR: [signature] DATE: 9-15-70 SHIFT: Day REVIEWED BY: [signature]

EXPERIMENTAL

INSPECTOR'S DAILY NARRATIVE

CONTRACT NO.	CONTRACTOR	WEATHER
113	Mario F. DeBona	Fair

Spraying Box Joint 54-55-62

INSPECTOR: [signature] DATE: 9-16-70 SHIFT: Day REVIEWED BY: [signature]

INSPECTOR'S DAILY NARRATIVE

CONTRACT NO.	CONTRACTOR	WEATHER
113	Mario & DeBono	Fair

Spraying Core Column 61

Spraying Box joint 63

3 men

INSPECTOR: [illegible] DATE: 9-24-70 SHIFT: Day REVIEWED BY

INSPECTOR'S DAILY NARRATIVE

CONTRACT NO.	CONTRACTOR	WEATHER
113	Mario & DeBono	

2 Sprayers — Tower B

3 Laborers — Tel-Co Area

1 Machine — 11 Fl.

1 Helper — Plasterers & laborers

First Coat as per sample on 10 Fl. on South & West Elevation

INSPECTOR: [illegible] DATE: 9/24/70 SHIFT: Day REVIEWED BY

EXPERIMENTAL

INSPECTOR'S DAILY NARRATIVE

CONTRACT NO.	CONTRACTOR	WEATHER
113	Mario & DeBono	Fair

Spraying fireproofing 61 fl. Core Columns & 63 fl. Box Joints

3 men

INSPECTOR: [illegible] DATE: 9-23-70 SHIFT: DAY REVIEWED BY

EXPERIMENTAL

INSPECTOR'S DAILY NARRATIVE

CONTRACT NO.	CONTRACTOR	WEATHER
113	Mario & DeBono	

Tower B

11 Fl. - Tel-Co

Two Plasterers, Three laborers spray on box joints as per sample —

Visitors of Tel-Co on inspection tour / Ed Boland & Writer.

INSPECTOR: [illegible] DATE: 9/21/70 SHIFT: Day REVIEWED BY

INSPECTOR'S DAILY NARRATIVE

CONTRACT NO.	CONTRACTOR	WEATHER
113	Mario & Di Bono	

Tower B
11 Fl - Tel-Co

2 Plasters - informed contractor that present application is not acceptable to Tel-Co; Will go over sample with them @ 1 PM

INSPECTOR: [illegible] DATE: 9/29/70 SHIFT: Day REVIEWED BY:

INSPECTOR'S DAILY NARRATIVE

CONTRACT NO.	CONTRACTOR	WEATHER
113	Mario & Di Bono	

10 & 11 Fl - Tel Co
Four Plasters, four laborers

1. Tony [illegible] has agreed to go back & re-strip [illegible] that are not as per sample
2. Overspray will start on 20 [illegible] [illegible] of NE [illegible] tomorrow, Tel-Co will come when same is finished.
3. "Q" deck overspray will also be started

INSPECTOR: [illegible] DATE: 9/29/70 SHIFT: Day REVIEWED BY:

EXPERIMENTAL
INSPECTOR'S DAILY NARRATIVE

CONTRACT NO.	CONTRACTOR	WEATHER
113	Mario & Di Bono	Fair

No work on this Contract today

INSPECTOR: [illegible] DATE: 9-28-70 SHIFT: Day REVIEWED BY:

EXPERIMENTAL
INSPECTOR'S DAILY NARRATIVE

CONTRACT NO.	CONTRACTOR	WEATHER
	10 FLOOR MOCK UP	

Tower "A"

1. Made tour this AM with Joe Carbone of TRCO noted the following:
   a) Circle acoustics not working (black iron)
   b) [illegible] not in [illegible] - informed Mr. Wunsche.
   c) Mr. Underhill is to come back.
   d) Marble strip to be set this AM
2. Will go over all items with TRCO this PM

INSPECTOR: [illegible] DATE: 9/28/70 SHIFT: Day REVIEWED BY:

EXPERIMENTAL
G-68

INSPECTOR'S DAILY NARRATIVE

CONTRACT NO.	CONTRACTOR	WEATHER
113	Mario F. DeBono	Fair

Spraying Box Joints 63-64 Section 65

Inspector: [illegible] Date: 9-30-70 Shift: Day Reviewed by:

EXPERIMENTAL
G-68

INSPECTOR'S DAILY NARRATIVE

CONTRACT NO.	CONTRACTOR	WEATHER
113	Mario & DeBono	

Tower "B-10 & 11 Ft

Three plasterers, Four, laborers spraying on (Tel-Co Area) & tamping trucks.

No work (corrective) done today on N.E. Quadrant same was mentioned to Mario & DeBono. Caution the (Supt.) Tony [illegible] on tamping

Inspector: [illegible] Date: 9/30/70 Shift: Day Reviewed by:

EXPERIMENTAL
G-68

INSPECTOR'S DAILY NARRATIVE

CONTRACT NO.	CONTRACTOR	WEATHER
113	Mario F. DeBono	Fair

Spraying Box Joints 63-64

Inspector: [illegible] Date: 9-28-70 Shift: Day Reviewed by:

EXPERIMENTAL
G-68

INSPECTOR'S DAILY NARRATIVE

CONTRACT NO.	CONTRACTOR	WEATHER
113	Mario F. DeBono	Fair

Spraying Box Joints 63-64 ft

Inspector: [illegible] Date: 9-29-70 Shift: Day Reviewed by:

INSPECTOR'S DAILY NARRATIVE

CONTRACT NO.	CONTRACTOR	WEATHER
113	Mario & Ali Bono	

Tower "B"
10 & 11 Ft. Tel-6

Four Plasterers, Four laborers spray on Trusses of 10 Ft + 11 with Band Tamping.

Mark II overspray will start this PM on NE Corner of 11 Ft. Contractor cautioned again on tamping of same

R H Otter — INSPECTOR | 10/1/70 — DATE | Day — SHIFT | REVIEWED BY

INSPECTOR'S DAILY NARRATIVE

CONTRACT NO.	CONTRACTOR	WEATHER
113	Mario & Ali Bono	

Tower B
10 & 11 Ft.

One Plasterer, One laborer on 11 Ft Mark II subject area not acceptable unless touch up tamping is done informed Mario & Ali Bono of this.
Cafco being applied to Trusses of 10 Ft. Three / plasterers 3 laborers

R H Otter — INSPECTOR | 10/2/70 — DATE | Day — SHIFT | REVIEWED BY

EXPERIMENTAL 8-68

INSPECTOR'S DAILY NARRATIVE CAVANNA 01

CONTRACT NO.	CONTRACTOR	WEATHER
113	Mario F DiBono	Cloudy/Rain

Spraying Box Joints 66-67-68-69

overspraying 29

[illegible] — INSPECTOR | 10-5-70 — DATE | Day — SHIFT | [illegible] — REVIEWED BY

EXPERIMENTAL 8-68

INSPECTOR'S DAILY NARRATIVE CAVANNA

CONTRACT NO.	CONTRACTOR	WEATHER
113	Mario & Ali Bono	

Tower B

5 plasterers, four laborers, 1 Box joints 9-13 Fls

(This contractor will work this pm on interior Cols)

Five men on interior Cols till 6 PM

R H Otter — INSPECTOR | 10/15/70 — DATE | Day (4:30-6:30) — SHIFT | [illegible] — REVIEWED BY

YIP-22

A 3033 10-70

INSPECTOR'S DAILY NARRATIVE

Contract No.	Contractor	Weather
113	MARIO & DI BONO	PARTLY CLOUDY

TOWER 'A'
ELEVATOR BANK D ZONE I SHAFTS 44, 45 & 46 TWO LABORERS CLEANING

ELEVATOR BANK A ZONE II SHAFTS 54 55 & 56 - SPRAYING OF MARK II OVER SPRAY.

Inspector: Lou Guadagno · Date: 5/26/71 · Shift: 8-4:30 · Reviewed by: CAW 5/27/71

FA 3033 10-70

INSPECTOR'S DAILY NARRATIVE

Contract No.	Contractor	Weather
113	MARIO & DI BONO	PARTLY CLOUDY

TOWER 'A'
ONE SPRAYER & ONE LABORER FURNISHED & INSTALLED MARK II OVER-SPRAY OF CAFCO SPRAY-ON FIRE PROOFING IN ELEVATOR BANK D, SHAFTS 44, 45 & 46

TOWER 'B'
NOT WORKING

Inspector: Lou Guadagno · Date: 5/26/71 · Shift: 8-4:30 · Reviewed by: CAW 5/27/71

C.A. Smith

A 3033 10-70

INSPECTOR'S DAILY NARRATIVE

Contract No.	Contractor	Weather
113	MARIO & DI BONO	CLOUDY

TOWER 'A'
1 SPRAYER & 1 LABORER - FURNISHED & INSTALLED SPRAY-ON FIREPROOFING OF STRUCTURAL STEEL BEAMS & COLUMNS AT ELEVATOR BANK C, SHAFTS 44, 45 & 46.

TOWER 'B'
FURNISHED & INSTALLED SPRAY-ON FIRE PROOFING OF STRUCTURAL STEEL IN CORE AREAS ON THE 75TH FLOOR.

Inspector: Lou Guadagno · Date: 5/21/71 · Shift: · Reviewed by: CAW 5/25/71

C.A. Smith

FA 3033 10-70

INSPECTOR'S DAILY NARRATIVE

Contract No.	Contractor	Weather
113	MARIO & DI BONO	PARTLY CLOUDY

TOWER 'A'
ELEVATOR BANK A ZONE II SHAFTS 54, 55 & 56 - SPRAY-ON FIRE PROOFING OF STRUCTURAL STEEL BEAMS & COLUMNS.

TOWER 'B'
FURNISHED & INSTALLED SPRAY-ON FIRE-PROOFING OF STRUCTURAL STEEL BEAMS & CORE COLUMNS ON THE 75TH FLOOR

Inspector: Lou Guadagno · Date: 5/20/71 · Shift: 8-4:30 · Reviewed by: CAW 5/24/71

PA 3033
10-70

INSPECTOR'S DAILY NARRATIVE

Contract No.	Contractor	Weather
113	MARIO & DI BONO	PARTLY CLOUDY

TOWER 'A'

BANK D ZONE I SHAFTS 45, 46 & 47 - CLEANING.
2 LABORERS

BANK 'A' ZONE II, SHAFTS 54, 55 & 56
SPRAYING MARK II OVER SPRAY ON
CHECKED FIREPROOFING.
ONE SPRAYER & ONE LABORER.

Inspector	Date	Shift	Reviewed by
[signature]	5/27/71	8-4:30	[initials] 6/1/71

PA 3033
10-70

INSPECTOR'S DAILY NARRATIVE

Contract No.	Contractor	Weather
113	MARIO & DI BONO	CLEAR

TOWER 'A'

FURNISHED & INSTALLED MARK II OVER-
SPRAY IN ELEVATOR BANK D ZONE I,
SHAFTS 44, 45 & 46

ONE SPRAYER & ONE LABORER

Inspector	Date	Shift	Reviewed by
[signature]	5/24/71	8-4:30	[initials] 5/25/71

PA 3033
10-70

INSPECTOR'S DAILY NARRATIVE

Contract No.	Contractor	Weather
113	MARIO & DI BONO	CLEAR

TOWER 'A'

ELEVATOR BANK D, ZONE I, SHAFTS 45, 46 & 47
2 LABORERS - CLEANING

ELEVATOR BANK 'A' ZONE II, SHAFTS 54, 55 & 56
ONE SPRAYER & ONE LABORER - SPRAYING OF
MARK II OVER SPRAY.

Inspector	Date	Shift	Reviewed by
[signature]	5/25/71	8-4:30	[initials] 6/1/71

DAILY NARRATIVE

CONTRACT NO.	CONTRACTOR	WEATHER
113	Mario & DeBono	Fair

Spraying Box Joints 66

Overspray 26

INSPECTOR	DATE	SHIFT	REVIEWED BY
[illegible signature]	10-5-70	DAY	CW

INSPECTOR'S DAILY NARRATIVE

CONTRACT NO.	CONTRACTOR	WEATHER
113	Mario & DeBono	

Tower "B"

Mark II overspray on 11 Ft. troweled along entire east-half, toured same with Tony Iaurenso of OTSD and pointed out defects.

10 Ft Coffee being applied, requested more tamping of them.

Approved Hand Plaster, Four Columns

Will call Mr. Neumann for an inspection

INSPECTOR	DATE	SHIFT	REVIEWED BY
[illegible signature]	10/5/70	Day	CW

INSPECTOR'S DAILY NARRATIVE

CONTRACT NO.	CONTRACTOR	WEATHER
113	Mario & DeBono	Fair

Spraying Box Joints 64-65

Overspray 25

INSPECTOR	DATE	SHIFT	REVIEWED BY
[illegible signature]	10-2-70	DAY	CW

INSPECTOR'S DAILY NARRATIVE

CONTRACT NO.	CONTRACTOR	WEATHER
113	Mario & DeBono	Fair

Spraying Conc Col 48-56-54-65-66-64

Spraying Beam 40

Overspray 25-26

N Plaster - 12 Lab 2 Foreman 1 Eng.

INSPECTOR	DATE	SHIFT	REVIEWED BY
[illegible signature]	10-3-70	DAY	CW

INSPECTOR'S DAILY NARRATIVE

CONTRACT NO.	CONTRACTOR	WEATHER
113	Mario & Di Bono	

Tower B

Spray bar joint on 9 Fl. & Interior Cols.

Touch up on 11 Fl.

INSPECTOR: [illegible] DATE: 10/7/70 SHIFT: 4 30 - 7 30 REVIEWED BY: [illegible]

INSPECTOR'S DAILY NARRATIVE CAVANAGH

CONTRACT NO.	CONTRACTOR	WEATHER
113	Mario & Di Bono	

Tower B

Contractor washed until 7 PM on Col. shafts (interior) from 9 to 11 Floor and touch up in Tel Co Area 11 Floor.

INSPECTOR: [illegible] DATE: 10/6/70 SHIFT: Day (4 30 - 7 30) REVIEWED BY: [illegible]

EXPERIMENTAL

INSPECTOR'S DAILY NARRATIVE CAVANAGH

CONTRACT NO.	CONTRACTOR	WEATHER
113	Mario & Di Bono	

Tower B

JEFF REVENE

Six Plasterers, four laborers, spray bar joints 9, 10, 11 & 12 on floors. Cofio (10-11 & 12 Tel Co)

Washed on exterior shafts and bar joints of 13 Fl from 4 30 to 7 PM

INSPECTOR: [illegible] DATE: 10/9/7 SHIFT: 8 AM - 7 PM REVIEWED BY: [illegible]

EXPERIMENTAL

INSPECTOR'S DAILY NARRATIVE CAVANAGH

CONTRACT NO.	CONTRACTOR	WEATHER
113	Mario & Di Bono	

Tower B

4 Plasters, 4 laborers internal shafts Cofio

INSPECTOR: [illegible] DATE: 10/10/70 SHIFT: Day REVIEWED BY: [illegible]

DAILY NARRATIVE

CONTRACT NO.	CONTRACTOR	WEATHER
113	Mario F. DeBono	Fair

Overspray 27-28
Bar joists 66-67-68
Pick up Core Columns thru 67

INSPECTOR	DATE	SHIFT	REVIEWED BY
[illegible]	10-7-70	Day	[illegible]

DAILY NARRATIVE

CONTRACT NO.	CONTRACTOR	WEATHER
113	Mario F. DeBono	Fair

Overspray 29
Bar joists 67-68
Pick up Core Columns

INSPECTOR	DATE	SHIFT	REVIEWED BY
[illegible]	10-9-70	Day	[illegible]

EXPERIMENTAL

INSPECTOR'S DAILY NARRATIVE

CONTRACT NO.	CONTRACTOR	WEATHER
113	Mario F. DeBono	

Tower B
Tile Co.

Cafco spray on 9 Fl.
Overspray Mark II on 11 Fl.
& Tamping
Tamping Ton 10 Fl & Cleaning
Three [illegible] 10 [illegible]

INSPECTOR	DATE	SHIFT	REVIEWED BY
[illegible]	10/6/70	Day	[illegible]

EXPERIMENTAL

INSPECTOR'S DAILY NARRATIVE

C. H. SMITH

CONTRACT NO.	CONTRACTOR	WEATHER
113	Mario F. DeBono	Fair

Overspray 27
Bar joists 66-67

INSPECTOR	DATE	SHIFT	REVIEWED BY
[illegible]	10-7-70	Days	[illegible]

INSPECTOR'S DAILY NARRATIVE

CONTRACT NO.	CONTRACTOR	WEATHER
113	Mario & Di Bono	

Tower "B"

Overspray (Mark II) being applied to 11 Fl. Tel Co. terminal. Cafco being applied to 10 Floor Tel-Co. Thirteenth floor also Cafco. Approx 4 plasterers 4 laborers.

Inspection today by Tel-Co ground rules laid out to Mario & Di Bono as to what final product should be.

INSPECTOR: [signature] DATE: 10/7/70 SHIFT: Day REVIEWED BY: [signature]

INSPECTOR'S DAILY NARRATIVE

CONTRACT NO.	CONTRACTOR	WEATHER
113	Mario & Di Bono	

Tower B

9-10-11-12 bar joists including tel-Co area

10 Plasterers & 10 Labors.

* Two plasters & two labors. 9-4 Floor

INSPECTOR: [signature] DATE: 10/8/70 SHIFT: Day (4:30/7:30) REVIEWED BY: [signature]

EXPERIMENTAL

INSPECTOR'S DAILY NARRATIVE

CONTRACT NO.	CONTRACTOR	WEATHER
113	Mario & Di Bono	

Tower B

15 Fl: 1 Plaster, 1 Labor

14 " : " "

10 " : " 3 "

6 on machine 1st floor

Spray - bar joists & Tel-Co Area with Mark II

NOTE: NORTH SIDE OF 10TH FLOOR 90%

INSPECTOR: [signature] DATE: 10/21/70 SHIFT: Day REVIEWED BY: [signature]

EXPERIMENTAL

INSPECTOR'S DAILY NARRATIVE

CONTRACT NO. 113	CONTRACTOR	WEATHER
C.O. 675067	Mario & Di Bono	cloudy w/ rain

2 men finished wrapping exhaust duct on 15th floor with first lot of wire lath, then proceeded to the 19th floor.

(Ducts as indicated on contract dwgs.

INSPECTOR: [signature] DATE: 10/26/70 SHIFT: 8-4:30 REVIEWED BY: [signature]

DAILY NARRATIVE

CONTRACT NO. 113 | CONTRACTOR Mario & Di Bono | WEATHER Fair

Spraying Bar Joists 66-67-68

INSPECTOR [signature] DATE 10-14-70 SHIFT Day REVIEWED BY [signature]

INSPECTOR'S DAILY NARRATIVE Cavanagh

CONTRACT NO. 113 | CONTRACTOR Mario & Di Bono | WEATHER Fair

Tower B

Fire laborer, 2 plasters Topping trusses of 12 F al Co
Four Plasters Making 11 Fl.
two on 10 Fl & Clean up

*Worked this PM on interior Cols

INSPECTOR [signature] DATE 10/13/70 SHIFT Day (*till 6PM) REVIEWED BY [signature]

EXPERIMENTAL

INSPECTOR'S DAILY NARRATIVE Cavanagh

CONTRACT NO. 113 | CONTRACTOR Mario & Di Bono | WEATHER

Tower B

8 plasters, 4 laborers, spray in Cafco of Trusses from 9th 13 fl
Made it on Top of flanges of 11th floor. and Topping of 10 Fl. Trusses.

Interior Cols & Trusses to be done from 4:30 to 6 PM

INSPECTOR [signature] DATE 10/14/70 SHIFT Day REVIEWED BY [signature]

EXPERIMENTAL

INSPECTOR'S DAILY NARRATIVE Cavanagh

CONTRACT NO. 113 | CONTRACTOR Mario & Di Bono | WEATHER Fair

Spraying Bar Joists 67-68

INSPECTOR [signature] DATE 10-13-70 SHIFT Day REVIEWED BY [signature]

DAILY NARRATIVE

CONTRACT NO.	CONTRACTOR	WEATHER
113	Mario & Di Bono	Windy Cold

(Sunday) Tower B

Mark II Pumping on Col-Co

10 & 11 Fl

Two Plasterers, four laborers

One Plasterer on Int. Col on 9 Fl

full appr 53rd

INSPECTOR: [illegible] DATE: 10/18 SHIFT: Day REVIEWED BY: [illegible]

EXPERIMENTAL 0-00

INSPECTOR'S DAILY NARRATIVE

CONTRACT NO.	CONTRACTOR	WEATHER
WTC 113.00	Mario & Di Bono	Clear-Mild

Tower "A" Core Column Work (8 AM to 4 PM)

Sketches to Wally [illegible]

5 Plasterers - 4 Laborers & 1 - Foreman

Floors Finished - Today 49-50-51-52-53-54-56-

57 1/2 Completed

46 - 3/4 Completed

INSPECTOR: [illegible] DATE: 10/12/70 SHIFT: 8 to 4:30 pm REVIEWED BY: [illegible]

EXPERIMENTAL 0-00

INSPECTOR'S DAILY NARRATIVE CAVANAGH

CONTRACT NO.	CONTRACTOR	WEATHER
113	Mario & Di Bono	

Tower B

5 plasterers, 6 labor - bar joists 13 & 12 Fl.

2 plasterers, 6 laborers 10 & 11 floors - Mark II

INSPECTOR: [illegible] DATE: 10/16/70 SHIFT: (8-4:30) REVIEWED BY: [illegible]

EXPERIMENTAL 0-00

INSPECTOR'S DAILY NARRATIVE CAVANAGH

CONTRACT NO.	CONTRACTOR	WEATHER
113	Mario & Di Bono	

Tower "B"

9 - 13 floors

Spray Cofer & Mark II on 10 & 11

4 plasterers 6 labor

INSPECTOR: [illegible] DATE: 10/19/70 SHIFT: Day REVIEWED BY: [illegible]

DAILY NARRATIVE

CONTRACT NO.	CONTRACTOR	WEATHER
113	Mario & DeBono	Fair

Spraying Bar Joists 66-67-68-69

[illegible] 10-17-70 Day [illegible]

INSPECTOR DATE SHIFT REVIEWED BY

INSPECTOR'S DAILY NARRATIVE

CONTRACT NO.	CONTRACTOR	WEATHER
113	Mario & DeBono	

Tower B

Saturday

Mack II on 10 & 11 (Tel-Co)

2 plasterers, 6 laborers.

Cafro - interior shafts - 2 plasterers

12 floor

[illegible] 10/17/70 Day [illegible]

INSPECTOR DATE SHIFT REVIEWED BY

DAILY NARRATIVE

CONTRACT NO.	CONTRACTOR	WEATHER
113	Mario & DeBono	Fair

Spraying Bar Joists 69-70

[illegible] 10-19-70 Day [illegible]

INSPECTOR DATE SHIFT REVIEWED BY

INSPECTOR'S DAILY NARRATIVE

CONTRACT NO.	CONTRACTOR	WEATHER
113	Mario & DeBono	

Tower B

3 plasterers on bar joists 13 & 14 [illegible]

2 " " Tel Co 10 & 11

and 8 laborers

[illegible] 10/20/70 Day [illegible]

INSPECTOR DATE SHIFT REVIEWED BY

INSPECTOR'S DAILY NARRATIVE

CONTRACT NO.	CONTRACTOR	WEATHER
IC 500.00, 74.00	10 FLOOR MOCK UP	

SUNDAY —

ABT - 12 [illegible] — inst. [illegible], panels, connectors.
Circle Acoustic — Black Iron
3 men cutting out drilling for ABT - so far 18 tile have been removed (need replacement)
Circle Acoustic - Ceiling - carpentry trade went home due to death Friday in Tower "B"

INSPECTOR: [signature] DATE: 10/2?/70 SHIFT: Day SB REVIEWED BY: [signature]

INSPECTOR'S DAILY NARRATIVE

CONTRACT NO.	CONTRACTOR	WEATHER
WIC 600.00, 42.00 110.00 115.00 124.00, 139.00	10 FLOOR MOCK-UP	

Tower "A"

Unger - 2-5 el. - wire, fixtures
ABT - 4 - panels, connectors
Sparklers 4.
Hudson Shade (Private) 2 - [illegible] wall
Circle Acoustics: Black Iron 3 -
Ceiling Tile 3 -
Circle Flooring - 95% Has Complete [illegible] for [illegible]
Jacks - [illegible] (95% complete.)

INSPECTOR: [signature] DATE: 10/23/70 SHIFT: Day SB REVIEWED BY: [signature]

EXPERIMENTAL

INSPECTOR'S DAILY NARRATIVE CAVANAGH

CONTRACT NO.	CONTRACTOR	WEATHER
113	Mario & Di Bono	Cloudy / Rain

Spraying Box Joints 20 - 21 - 22

INSPECTOR: [signature] DATE: 10-21-70 SHIFT: Day SB REVIEWED BY: [signature]

EXPERIMENTAL

INSPECTOR'S DAILY NARRATIVE CAVANAGH

CONTRACT NO.	CONTRACTOR	WEATHER
113	Mario & Di Bono	

Tower "B"

1 plaster 15 Floor
2 " 14 " } using 8 laborers
1 " 6 "

4 plasterers 2 laborers North Side of 10 Floor. (Tel-Co)

INSPECTOR: [signature] DATE: 10/21/70 SHIFT: Day SB REVIEWED BY: [signature]

DAILY NARRATIVE

CONTRACT NO.	CONTRACTOR	WEATHER
113	Macci & DiBono	Fair

Spraying Bar joints 69-70-71 fl

INSPECTOR: [illegible] DATE: 10-21-70 SHIFT: Day REVIEWED BY: [illegible]

DAILY NARRATIVE

CONTRACT NO.	CONTRACTOR	WEATHER
113	Macci & DiBono	Rain

Spraying Bar joints 71-71-72

Worked till 1:30 PM Rain

INSPECTOR: [illegible] DATE: 10-22-70 SHIFT: Day [illegible] REVIEWED BY: [illegible]

EXPERIMENTAL

INSPECTOR'S DAILY NARRATIVE

CAVANAGH

CONTRACT NO.	CONTRACTOR	WEATHER
WTC 11200 / TAYE 575067	Macco & Bono	clear & mild

2 men started wrapping ducts on 18th floor with wire mesh for vermiculite.
Worked from 12 pm to 3 pm
or five people

INSPECTOR: [illegible] DATE: 10/20/70 SHIFT: 8-4 REVIEWED BY: [illegible]

EXPERIMENTAL

INSPECTOR'S DAILY NARRATIVE

CAVANAGH

CONTRACT NO.	CONTRACTOR	WEATHER
113	Marco & Di Bono	

Tower B

15 floor 1 plaster 1-laborer
14 3 " 3- "
6 machine " 3 10 1 lab

Bar joist - and Mark II fume where dry on N. Side 10 fl

INSPECTOR: [illegible] DATE: 10/23/70 SHIFT: Day [illegible] REVIEWED BY: [illegible]

INSPECTOR'S DAILY NARRATIVE

CONTRACT NO.	CONTRACTOR	WEATHER
113	Marie & Klo Jones	

Tower B

15 Barjoist 2 floors
14 " 2
6 " 2
Total 8 labor

10 Floor Tel-Co N. Side
2 on Mark II after 4 to 8 PM
Area complete.

INSPECTOR	DATE	SHIFT		REVIEWED BY
R Hoff	10/26/70	Day	SfB	DW

DAILY NARRATIVE

CONTRACT NO.	CONTRACTOR	WEATHER
113	Marie F. DeBorn	Cloudy

Spraying Bar Joists 71-22-23-24

INSPECTOR	DATE	SHIFT		REVIEWED BY
W Schlief	10-27-70	Day	SfB	DW

EXPERIMENTAL

INSPECTOR'S DAILY NARRATIVE

CONTRACT NO.	CONTRACTOR	WEATHER
113	Marie F. DeBorn	Cloudy - Rain

Spraying Bar Joist 70-21-22

INSPECTOR	DATE	SHIFT		REVIEWED BY
W Schlief	10-23-70	Day	SfB	CW

EXPERIMENTAL

INSPECTOR'S DAILY NARRATIVE

CONTRACT NO.	CONTRACTOR	WEATHER
113	Marie F. DeBorn	Cloudy

Spraying Bar Joists 71-22-24

INSPECTOR	DATE	SHIFT		REVIEWED BY
W Schlief	10-26-70	Day	SfB	DW

DAILY NARRATIVE

CONTRACT NO.	CONTRACTOR	WEATHER
113	Mario & DeBono	Fair

Spraying Fireproofing 71-72-73-74

INSPECTOR	DATE	SHIFT		REVIEWED BY
[signature]	10-29-70	Day	[illegible]	[signature]

DAILY NARRATIVE

CONTRACT NO.	CONTRACTOR	WEATHER
113	Mario & DeBono	Fair

Spraying Cafes Bar Joist
71-72-73-74

INSPECTOR	DATE	SHIFT		REVIEWED BY
[signature]	10-30-70	Day	[illegible]	[signature]

EXPERIMENTAL 8-68

INSPECTOR'S DAILY NARRATIVE

CONTRACT NO.	CONTRACTOR	WEATHER
113	Mario & DeBono	

Tower B
Spray bay posts 5 Floor
three labor 15 & 16 Floor
2 on 310 2 labors

INSPECTOR	DATE	SHIFT		REVIEWED BY
[signature]	10/29/70	Day	[illegible]	[signature]

EXPERIMENTAL 8-68

INSPECTOR'S DAILY NARRATIVE

CONTRACT NO.	CONTRACTOR	WEATHER
113	Mario & DeBono	

Tower B
2 Plasters on 6 Ft
2 " " 15 } 5 labors
2 " 16
2 on Tile-Co Areas
Touch up

INSPECTOR	DATE	SHIFT		REVIEWED BY
[signature]	10/29/70	Day	[illegible]	[signature]

DAILY NARRATIVE

CONTRACT NO.	CONTRACTOR	WEATHER
113	Mario & DiBono	Fair

Spraying fireproofing 71-72-73-74

INSPECTOR: [illegible] DATE: 10-28-70 SHIFT: Day [illegible] REVIEWED BY: [illegible]

EXPERIMENTAL

INSPECTOR'S DAILY NARRATIVE

CONTRACT NO.	CONTRACTOR	WEATHER
113	Mario & DiBono	

Tower B

3 Plasterers & 4 laborers on Til-Co Area

Mark II, Tamping & touch up on 'Cafco.'

INSPECTOR: [illegible] DATE: 10/27 & 10/28 SHIFT: Day (1336) [illegible] REVIEWED BY: [illegible]

EXPERIMENTAL

INSPECTOR'S DAILY NARRATIVE

CONTRACT NO.	CONTRACTOR	WEATHER
113	Mario & DiBono	

Tower B

15
14
6
12
13
10
11
} Clean up & bar joist / Cafco

INSPECTOR: [illegible] DATE: 10/27/70 SHIFT: Day [illegible] REVIEWED BY: [illegible]

EXPERIMENTAL

INSPECTOR'S DAILY NARRATIVE

CONTRACT NO.	CONTRACTOR	WEATHER
113	Mario & DiBono	

Tower "B"

15
14
13
12
11
10
} bar joists - Cafco & Clean up

INSPECTOR: [illegible] DATE: 10/28/70 SHIFT: Day [illegible] REVIEWED BY: [illegible]

DAILY NARRATIVE

CONTRACT NO.	CONTRACTOR	WEATHER
113	[illegible]	[illegible]

[illegible] 24-25 26-27

INSPECTOR	DATE	SHIFT	REVIEWED BY
[illegible]	11-2-70	Day	[illegible]

DAILY NARRATIVE

CONTRACT NO.	CONTRACTOR	WEATHER
113	Mario & DiBono	Fair

Spraying fireproofing 24-25-26-27

INSPECTOR	DATE	SHIFT		REVIEWED BY
[illegible]	11-3-70	Day	[illegible]	[illegible]

DAILY NARRATIVE

CONTRACT NO.	CONTRACTOR	WEATHER
113	Mario & DiBono	Fair

Spraying fireproofing 25-26-27 Fl

INSPECTOR	DATE	SHIFT		REVIEWED BY
[illegible]	11-4-70	Day	[illegible]	[illegible]

EXPERIMENTAL 0-88

INSPECTOR'S DAILY NARRATIVE

CONTRACT NO.	CONTRACTOR	WEATHER
113	Mario & DiBono	

Tower B

11 Floor - Touch ups &

Mech Fl (Tel-Co)

2 Floor & 16 Floor (bar joists)

Using 6 plasterers & 5 labors

(inspector calls this PM)

INSPECTOR	DATE	SHIFT		REVIEWED BY
[illegible]	11/2/70	Day	[illegible]	[illegible]

EXPERIMENTAL 0-88

INSPECTOR'S DAILY NARRATIVE

CONTRACT NO.	CONTRACTOR	WEATHER
113	Mario & DiBono	

Tower B

17 & 18 Floor bar joists

11 Fl Tel-Co

6 plasterers 4 labors

INSPECTOR	DATE	SHIFT		REVIEWED BY
[illegible]	11/3/70	Day	[illegible]	[illegible]

EXPERIMENTAL 8-68

INSPECTOR'S DAILY NARRATIVE

CONTRACT NO.	CONTRACTOR	WEATHER
113	Mario & DeBona	Fair

Spraying fireproofing 75-76-77 floors

INSPECTOR	DATE	SHIFT		REVIEWED BY
[illegible signature]	11-5-70	DAY	8½	[illegible initials]

EXPERIMENTAL 8-68

INSPECTOR'S DAILY NARRATIVE

CONTRACT NO.	CONTRACTOR	WEATHER
113	Mario & DeBona	Fair

Spraying 76-77-78

INSPECTOR	DATE	SHIFT		REVIEWED BY
[illegible signature]	11-6-70	DAY	8½	[illegible initials]

EXPERIMENTAL 8-68

INSPECTOR'S DAILY NARRATIVE

CONTRACT NO.	CONTRACTOR	WEATHER
113	Mario & DeBona	

16 & 17 Fl bar joists -
Tel Co 11 Fl -
4 plasters 4 laborers

INSPECTOR	DATE	SHIFT		REVIEWED BY
[illegible signature]	11/4/70	Day	8½	[illegible initials]

EXPERIMENTAL 8-68

INSPECTOR'S DAILY NARRATIVE

CONTRACT NO.	CONTRACTOR	WEATHER
113	Mario & DeBona	

Tower "B"
17 18 Floor bar joists
11 Floor patch Tel Co Area
5 plasters 6 laborers

INSPECTOR	DATE	SHIFT		REVIEWED BY
[illegible signature]	11/5/70	Day	8½	[illegible initials]

INSPECTOR'S DAILY NARRATIVE

CONTRACT NO. 113 | CONTRACTOR Mario & Di Bono | WEATHER

Tower B

11 Fl: Tel-Co Mark II

18 & 19 Fl: bar joists

8 plasterers 4 + 2 labor

INSPECTOR [signature] | DATE 11/9/70 | SHIFT Day | EB | REVIEWED BY [signature]

INSPECTOR'S DAILY NARRATIVE

CONTRACT NO. 113 | CONTRACTOR Mario & Di Bono | WEATHER

Tower B

11 Fl Tel Co Mark II

12 " " "

18 & 19 Floor Cofco

on bar joists

10 plasterers & labor

INSPECTOR [signature] | DATE 11/10/70 | SHIFT Day | EB | REVIEWED BY [signature]

EXPERIMENTAL

INSPECTOR'S DAILY NARRATIVE

CONTRACT NO. 113 | CONTRACTOR Mario & Di Bono | WEATHER

Tower B

(1) Mark II overspray Tel-Co

& Touch ups some & Clean

2 Plaster 4 labor

(2) Herb Weinberg will be told Monday to pull out all stops on partition final preparations

INSPECTOR [signature] | DATE 11/7/70 | SHIFT Day | EB | REVIEWED BY [signature]

EXPERIMENTAL

INSPECTOR'S DAILY NARRATIVE

CONTRACT NO. 113 | CONTRACTOR Mario & DeBono | WEATHER Fair

Spraying fireproofing 25-28

INSPECTOR [signature] | DATE 11-9-70 | SHIFT Day | EB | REVIEWED BY [signature]

INSPECTOR'S DAILY NARRATIVE

CONTRACT NO.	CONTRACTOR	WEATHER
113	Mario & Di Bono	

Tower B
4 on 11 Fl (plasters on bar joints)
4 plasters on bar plates
18 & 19 Fl

INSPECTOR	DATE	SHIFT	REVIEWED BY
[signature]	11/11 & 11/12/80	Day	[signature]

EXPERIMENTAL

INSPECTOR'S DAILY NARRATIVE

CONTRACT NO.	CONTRACTOR	WEATHER
113	Mario & Di Bono	

Tower B
29 Fl
26 Fl
20 "
21 "
310 level
12 Fl Tel-Co
} 8 plasters 6 laborers

Note Tel-Co Area 11 Fl available PM WED. for inspection by Tel Co Rep.

INSPECTOR	DATE	SHIFT	REVIEWED BY
[signature]	11/14/80	Day	[signature]

EXPERIMENTAL

INSPECTOR'S DAILY NARRATIVE

CONTRACT NO.	CONTRACTOR	WEATHER
113	Mario & Di Bono	Rain

Spraying 75 - 78 floors fireproofing

INSPECTOR	DATE	SHIFT	REVIEWED BY
W. Sehlert	11-10-80	Day	[signature]

EXPERIMENTAL

INSPECTOR'S DAILY NARRATIVE

CONTRACT NO.	CONTRACTOR	WEATHER
113	Mario & Di Bono	Rain

Spraying fireproofing 75-78 fl

INSPECTOR	DATE	SHIFT	REVIEWED BY
W. Sehlert	11-11-80	Day	[signature]

EXPERIMENTAL
0-00

INSPECTOR'S DAILY NARRATIVE

CONTRACT NO.	CONTRACTOR	WEATHER
113	Mario F. DeBono	

Tunnel "B"

Box joint on 19 - 2' fiberglass
20 " "
24 "
25 1 "
Tun-C 10 ft - 2' fiberglass patch around shaft
using Ten laborers

[illegible]	11/13/70	Day	[illegible]
INSPECTOR	DATE	SHIFT	REVIEWED BY

EXPERIMENTAL
0-00

INSPECTOR'S DAILY NARRATIVE

CONTRACT NO.	CONTRACTOR	WEATHER
113	Mario F. DeBono	Fair

Spraying Shafts 25-26-28-29

[illegible]	11-[illegible]	Day	[illegible]
INSPECTOR	DATE	SHIFT	REVIEWED BY

EXPERIMENTAL
0-00

INSPECTOR'S DAILY NARRATIVE

CONTRACT NO.	CONTRACTOR	WEATHER
113	Mario F. DeBono	Rain/Cloudy

Spraying Cafco Fireproofing 25-28 fl.

[illegible]	11-12-70	Day	[illegible]
INSPECTOR	DATE	SHIFT	REVIEWED BY

EXPERIMENTAL
0-00

INSPECTOR'S DAILY NARRATIVE

CONTRACT NO.	CONTRACTOR	WEATHER
113	Mario DeBono	Rain

Spraying fireproofing on Box Joints & Core Columns 25 26 27-28

[illegible]	11-13-70	Day	[illegible]
INSPECTOR	DATE	SHIFT	REVIEWED BY

EXPERIMENTAL
8-68

INSPECTOR'S DAILY NARRATIVE

CONTRACT NO.	CONTRACTOR	WEATHER
113	Mario F. DeBone	Fair

Spraying fireproofing 79-80 fl.

INSPECTOR	DATE	SHIFT		REVIEWED BY
[illegible signature]	11-18-70	DAY	[illegible]	[illegible signature]

EXPERIMENTAL
8-68

INSPECTOR'S DAILY NARRATIVE

CONTRACT NO.	CONTRACTOR	WEATHER
113	Mario F. DeBone	Cloudy / fair

Spraying 79-80 floor

INSPECTOR	DATE	SHIFT		REVIEWED BY
[illegible signature]	11-19-70	Day	[illegible]	[illegible signature]

EXPERIMENTAL
8-68

INSPECTOR'S DAILY NARRATIVE

CONTRACT NO.	CONTRACTOR	WEATHER
113	Mario F. DeBone	Fair

Spraying Bar joist 79 floor

INSPECTOR	DATE	SHIFT		REVIEWED BY
[illegible signature]	11-16-70	Day	[illegible]	[illegible signature]

EXPERIMENTAL
8-68

INSPECTOR'S DAILY NARRATIVE

CONTRACT NO.	CONTRACTOR	WEATHER
113	Mario F. DeBone	Fair

Spraying Bar joist 78-80

INSPECTOR	DATE	SHIFT		REVIEWED BY
[illegible signature]	11-17-70	Day	[illegible]	[illegible signature]

8-68

DAILY NARRATIVE

CONTRACT NO.	CONTRACTOR	WEATHER
113	Mario & Di Bono	

Tower B 10812

4 Plasters Tel-Co floors 2-84 level.

Six Laborers.

INSPECTOR	DATE	SHIFT		REVIEWED BY
[signature]	11/21/70	Day	[initials]	[initials]

EXPERIMENTAL 8-68

INSPECTOR'S DAILY NARRATIVE

CONTRACT NO.	CONTRACTOR	WEATHER
113	Mario & Di Bono	Fair

Spraying R&F Box Joists

11 fl Corrugated Touchup & Patch

INSPECTOR	DATE	SHIFT		REVIEWED BY
[signature]	11-23-70	DAY	[initials]	[initials]

EXPERIMENTAL 8-68

INSPECTOR'S DAILY NARRATIVE

CONTRACT NO.	CONTRACTOR	WEATHER
113	Mario & Di Bono	Fair

Spraying Fireproofing R&F.

Touchup on 11 floor

INSPECTOR	DATE	SHIFT		REVIEWED BY
[signature]	11-20-70	DAY	[initials]	[initials]

EXPERIMENTAL 8-68

INSPECTOR'S DAILY NARRATIVE

CONTRACT NO.	CONTRACTOR	WEATHER
113	Mario & Di Bono	

Tower B

25 & 26 floor Box Joists &

Mark IF 10 floor

8 Plasterers 8 Laborers

INSPECTOR	DATE	SHIFT		REVIEWED BY
[signature]	11/20/70	Day	[initials]	[initials]

DAILY NARRATIVE

CONTRACT NO.	CONTRACTOR	WEATHER
113	Mario & Di Bono	25° High Wind

Tower B

To Cold for Crafts &
on 11/25 Water pipe
break.

INSPECTOR	DATE	SHIFT		REVIEWED BY
[illegible]	11/24 & 11/25 1970	Day	S/B	C.W.

EXPERIMENTAL
INSPECTOR'S
DAILY NARRATIVE

CONTRACT NO.	CONTRACTOR	WEATHER
113	Mario & Di Bono	Fair, Cold

No Work on this Contract Too Cold.

INSPECTOR	DATE	SHIFT		REVIEWED BY
[illegible]	11-25-70	DAY	S/B	C.W.

EXPERIMENTAL
INSPECTOR'S
DAILY NARRATIVE

CONTRACT NO.	CONTRACTOR	WEATHER
113	Mario & Di Bono	

Tower B
29 Fl 22 floor 24 floor
4 10 & 12 tel-No Area
12 Men. for patch.

INSPECTOR	DATE	SHIFT		REVIEWED BY
[illegible]	11/27/70	Day	S/B	C.W.

EXPERIMENTAL
INSPECTOR'S
DAILY NARRATIVE

CONTRACT NO.	CONTRACTOR	WEATHER
113	Mario & Di Bono	Fair

No Work on this Contract Too Cold -
2 Teams coming in the PM to touch up
& Patch on 1st floor.

INSPECTOR	DATE	SHIFT		REVIEWED BY
[illegible]	11-24-70	DAY	S/B	C.W.

EXPERIMENTAL 0-00

INSPECTOR'S DAILY NARRATIVE

CONTRACT NO.	CONTRACTOR	WEATHER
113	Mario & Eli Bono [illegible]	Fair

No Work on the Contract. Water on & off all Day.

H Schlecht — INSPECTOR | 11-30-70 — DATE | Day — SHIFT | [illegible] C[illegible] — REVIEWED BY

0-00

INSPECTOR'S DAILY NARRATIVE

CONTRACT NO.	CONTRACTOR	WEATHER
113	Mario & Eli Bono	

Tower B

Started & Stopped Copes due to cut off in Water.
29 Floor; 24 Floor.
10 & 12 Floors

[illegible] — INSPECTOR | 11/30/70 — DATE | Day — SHIFT | [illegible] C[illegible] — REVIEWED BY

EXPERIMENTAL 0-00

INSPECTOR'S DAILY NARRATIVE

CONTRACT NO.	CONTRACTOR	WEATHER
113	Mario & Eli Bono	

Tower "B"

29-22-23 24 10 & 12
12 plasters 10 labores
bar posts & Til-Co

[illegible] — INSPECTOR | 11/27/70 — DATE | Day — SHIFT | [illegible] C[illegible] — REVIEWED BY

EXPERIMENTAL 0-00

INSPECTOR'S DAILY NARRATIVE

CONTRACT NO.	CONTRACTOR	WEATHER
113	Mario & Eli Bono [illegible]	Fair

No Work. No Water.

H Schlecht — INSPECTOR | 11-27-70 — DATE | Day — SHIFT | [illegible] C[illegible] — REVIEWED BY

EXPERIMENTAL 8-68

CM-SMITH.

INSPECTOR'S DAILY NARRATIVE

CONTRACT NO.	CONTRACTOR	WEATHER
113	MARIO & DI BONO	FAIR

TOWER 'B'
FURNISHED AND INSTALLED SPRAYON FIREPROOFING ON BAR JOISTS AND CORE COLUMNS ON FLOORS 24, 25, & 29.
SPRAYED CAFECO SEALER ON THE 10TH FLOOR.

INSPECTOR	DATE	SHIFT		REVIEWED BY
[signature]	12/2/70	8-4:30	S/T	[signature]

EXPERIMENTAL 8-68

XIP-22

INSPECTOR'S DAILY NARRATIVE

CONTRACT NO.	CONTRACTOR	WEATHER
113	Mario & Di Bono	

Tower B
24-25-24 floors
in Cafco
46 plasterers & laborers.

INSPECTOR	DATE	SHIFT		REVIEWED BY
[signature]	12/3/70		S/T	[signature]

EXPERIMENTAL 8-68

INSPECTOR'S DAILY NARRATIVE

CONTRACT NO.	CONTRACTOR	WEATHER
113	Mario & Di Bono	

Tower B
10 Fl - Touch up around partition.
11 Fl Mark II
18 Fl Cafco
8 Plasterers 6 labor

INSPECTOR	DATE	SHIFT		REVIEWED BY
[signature]	11/6/70	Day	S/T	[signature]

0-60

INSPECTOR'S DAILY NARRATIVE

CONTRACT NO.	CONTRACTOR	WEATHER
113	Marco & Di Bono	

Tower B

Held up - no water -

NOTE
ED. BOLAND → Bring in Tel-Co Pip on
2/8/70 [illegible] 10 & 12 floors Mark II
Complete except only
Cells on 12 floor - they
went up far as they could go.

INSPECTOR	DATE	SHIFT		REVIEWED BY
[illegible]	12/7/70	Day	8/3	[illegible]

XIP-22

EXPERIMENTAL 0-60

INSPECTOR'S DAILY NARRATIVE

CONTRACT NO.	CONTRACTOR	WEATHER
113	Marco & Di Bono	Fair

3 men 1 machine Patching 10 floor 4 PM
10 PM - Took water from 9 [illegible] through #3 stairway
12-4 [illegible] floor clean up -

INSPECTOR	DATE	SHIFT		REVIEWED BY
[illegible]	12-9-70	Day	8/3	[illegible]

EXPERIMENTAL 0-60

INSPECTOR'S DAILY NARRATIVE

CONTRACT NO.	CONTRACTOR	WEATHER
113	Marco & Di Bono	Fair

No Work [illegible] Contract Tower A
No Water - for [illegible]
[illegible] Di Bono [illegible]
[illegible] --

INSPECTOR	DATE	SHIFT		REVIEWED BY
[illegible]	12-4-70	Day	8/3	[illegible]

EXPERIMENTAL 0-60

INSPECTOR'S DAILY NARRATIVE

CONTRACT NO.	CONTRACTOR	WEATHER
113	Marco & Di Bono	

Very little work done due
to cold & ~~[illegible]~~
Shifting material
General Cleanup

INSPECTOR	DATE	SHIFT		REVIEWED BY
[illegible]	12/4/70	Day	8/3	[illegible]

YIP-22

INSPECTOR'S DAILY NARRATIVE

CONTRACT NO.	CONTRACTOR	WEATHER
113	MARIO & DI BONO	CLOUDY

TOWER A.

ONE PLASTERER AND ONE LABORER. SPRAY-ON FIRE PROOFING ON CORE STEEL IN ELEVATOR BANK 'B'. WORKING IN P.E. #33, 34 & 35. THIS WORK IS 75% COMPLETE.

INSPECTOR: [signature] DATE: 12/11/70 SHIFT: 8-4:30 [initials] REVIEWED BY: [initials]

INSPECTOR'S DAILY NARRATIVE

CONTRACT NO.	CONTRACTOR	WEATHER
113	Mario & Di Bono	-

Tower 'B'

30 - 27 floor Coping

8 plasterers & laborers —

INSPECTOR: [signature] DATE: 12/14/70 SHIFT: Day [initials] REVIEWED BY: [initials]

INSPECTOR'S DAILY NARRATIVE

CONTRACT NO.	CONTRACTOR	WEATHER
113	Mario & Di Bono	Fair

1 Fore. 2 Mechanics Patching 12 floor

4 PM - 10 PM - 12 fl Completed Drying

Equipment to 13 floor - to Continue

Patching

INSPECTOR: [signature] DATE: 12-10-70 SHIFT: [illegible] [initials] REVIEWED BY: [initials]

INSPECTOR'S DAILY NARRATIVE

CONTRACT NO.	CONTRACTOR	WEATHER
113	MARIO & DI BONO	FAIR

TOWER 'A'

ONE PLASTERER AND ONE LABORER. SPRAY-ON FIRE DAMPING IN ELEVATOR BANK 'B' P.E. CABS #. 33, 34 & 35. CONTRACTOR IS SPRAYING ONE HATCH AT A TIME.

INSPECTOR: [signature] DATE: 12/10/70 SHIFT: 8-4:30 [initials] REVIEWED BY: [initials]

YIP-22

INSPECTOR'S DAILY NARRATIVE

CONTRACT NO.	CONTRACTOR	WEATHER
113	MARIO & DI BONO	COLD-RAIN

TOWER 'B'

SPRAY-ON FIRE PROOFING ON BAR JOISTS AND CORE COLUMNS ON THE 28TH AND 40TH FLOORS.

INSPECTOR: [signature] DATE: 12/17/70 SHIFT: 8-4:30 REVIEWED BY: [signature]

INSPECTOR'S DAILY NARRATIVE

CONTRACT NO.	CONTRACTOR	WEATHER
113	MARIO & DI BONO	RAIN & COLD

TOWER 'A'

SPRAYED CAFECO SEALER ON SPRAY-ON FIRE PROOFING IN ELEV. BANK 'B' P.E. CARS 33, 34 & 35. WORK IN THESE HATCHES ARE 90% COMPLETE.

INSPECTOR: [signature] DATE: 12/17/70 SHIFT: 8-4:30 REVIEWED BY: [signature]

INSPECTOR'S DAILY NARRATIVE

CONTRACT NO.	CONTRACTOR	WEATHER
113	MARIO & DI BONO	SUNNY & COLD

TOWER 'A'

ONE PLASTERER AND ONE LABORER. SPRAY-ON FIRE PROOFING ON CORE STEEL IN ELEVATOR BANK 'B' P.E. CARS # 33, 34 & 35. WORK IN THESE HATCHES IS 85% COMPLETE.

INSPECTOR: [signature] DATE: 12/14/70 SHIFT: 8-4:30 REVIEWED BY: [signature]

INSPECTOR'S DAILY NARRATIVE

CONTRACT NO.	CONTRACTOR	WEATHER
113	MARIO & DI BONO	SUNNY & COLD

TOWER 'A'

APPLICATION OF CAFECO SEALER IN ELEVATOR BANK 'B' P.E. CARS # 33, 34 & 35. WORK IN THESE IS 85% COMPLETE.

INSPECTOR: [signature] DATE: 12/15/70 SHIFT: 8-4:30 REVIEWED BY: [signature]

XIP-22

INSPECTOR'S DAILY NARRATIVE

CONTRACT NO.	CONTRACTOR	WEATHER
113	Mario & Di Bono	

Tower "B"

30, 27, 26 floors - bar joists

g with Cafco

8 plasters & laborers.

INSPECTOR [illegible] DATE 12/9/70 SHIFT Day [illegible] REVIEWED BY [illegible]

C.A. SMITH

INSPECTOR'S DAILY NARRATIVE

CONTRACT NO.	CONTRACTOR	WEATHER
113	Mario & Di Bono	

Tower B

30 - 27 & 26 floors - Cafco

spray in bar joist.

Six plasters 5 laborers

INSPECTOR [illegible] DATE 12/10/70 SHIFT Day [illegible] REVIEWED BY [illegible]

C.A. SMITH

EXPERIMENTAL

INSPECTOR'S DAILY NARRATIVE

CONTRACT NO.	CONTRACTOR	WEATHER
113	MARIO & DI BONO	Cloudy - cold.

TOWER 'B'

SPRAY-ON FIREPROOFING ON BAR JOISTS AND CORE STRUCTURAL STEEL ON THE 28TH AND 40TH FLOORS.

INSPECTOR [illegible] DATE 12/16/70 SHIFT 8-4:30 [illegible] REVIEWED BY [illegible]

EXPERIMENTAL

INSPECTOR'S DAILY NARRATIVE

CONTRACT NO.	CONTRACTOR	WEATHER
113	MARIO & DI BONO	Cloudy - cold.

TOWER 'B'

APPLIED CAFCO SEALER TO SPRAY-ON FIREPROOFING IN ELEVATOR BANK 'B' PE. CARS 33, 34 & 36. WORK IN THESE HATCHES IS 85% COMPLETE.

INSPECTOR [illegible] DATE 12/16/70 SHIFT 8-4:30 [illegible] REVIEWED BY [illegible]

INSPECTOR'S DAILY NARRATIVE

T NO.	CONTRACTOR	WEATHER
	MARIO & DI BONO	COLD-SNOW.

[T]ER A.
[EL]EVATOR BANK B. CONTRACTOR
[CLE]ANING DOWN HATCHES 33, 34
35 – USING A ONE CAR OPERATION
[CON]TRARY TO THE THREE CAR
[OPE]RATION PREVIOUSLY DISCUSSED
[..]Y TACC. WORK IN BANK B IS 90% COMPLETE.
[ELE]VATOR BANK A – CONTRACTOR IS
[..]Y – FIRE PROOFING IN P.E. CARS 24, 25.

[Inspector signature] — INSPECTOR; [illegible] — DATE; 8-4:30 — SHIFT; [signature] — REVIEWED BY

EXPERIMENTAL 0-00

Y1P-22

INSPECTOR'S DAILY NARRATIVE

CONTRACT NO.	CONTRACTOR	WEATHER
113	MARIO & DI BONO	COLD – SNOW

TOWER 'B'

NO WORK. COLD WEATHER.

Lou Guadagno — INSPECTOR; 12/22/70 — DATE; 8-4:30 — SHIFT; [signature] — REVIEWED BY

C.A. SMITH

INSPECTOR'S DAILY NARRATIVE

T NO.	CONTRACTOR	WEATHER
[..]E BANK B – TOWER 'A'		COLD.

MARIO & DI BONO
[CH]ECKED APPLICATION OF CAFECO
[SEA]LER ON SPRAY-ON FIRE PROOFING
P.E. CARS 33, 34 & 35.

[..]Guadagno — INSPECTOR; 12/18/70 — DATE; 8-4:30 — SHIFT; [signature] — REVIEWED BY

EXPERIMENTAL 0-00

C.A. SMITH

INSPECTOR'S DAILY NARRATIVE

CONTRACT NO.	CONTRACTOR	WEATHER
113	MARIO & DI BONO	COLD

TOWER B.
SPRAY-ON FIRE PROOFING ON BAR
JOISTS AND CORE COLUMNS ON
THE 28TH AND 40TH FLOORS.

Lou Guadagno — INSPECTOR; 12/18/70 — DATE; 8-4:30 — SHIFT; [signature] — REVIEWED BY

YIP-22

INSPECTOR'S DAILY NARRATIVE

CONTRACT NO.	CONTRACTOR	WEATHER
113	MARIO & DI BONO	COLD-SUNNY

TOWER B.

NOT WORKING - COLD WEATHER

INSPECTOR	DATE	SHIFT		REVIEWED BY
Lou Dicadegna	12/28/70	8-4:30		CA

INSPECTOR'S DAILY NARRATIVE

CONTRACT NO.	CONTRACTOR	WEATHER
113	MARIO & DI BONO	COLD: SUNNY

TOWER 'A'

BANK 'A' SPRAY-ON FIRE PROOFING IN P.E. CARS # 24, 25 & 26 - 50% COMPLETE.

BANK 'B' CLEANING IN P.E. CARS 33, 34 & 35. 90% COMPLETE.

INSPECTOR	DATE	SHIFT		REVIEWED BY
Lou Dicadegna	12/28/70	8-4:30		CA

INSPECTOR'S DAILY NARRATIVE

CONTRACT NO.	CONTRACTOR	WEATHER
113	MARIO & DI BONO	COLD-SNOW

TOWER 'B'

SPRAY-ON FIRE PROOFING OF BAR JOISTS AND CORE COLUMNS ON THE 31ST AND 40TH FLOORS.

INSPECTOR	DATE	SHIFT		REVIEWED BY
Lou Dicadegna	12/29/70	8-4:30		CA

INSPECTOR'S DAILY NARRATIVE

CONTRACT NO.	CONTRACTOR	WEATHER
113	MARIO & DI BONO	COLD - SNOW

TOWER 'A'

ELEVATOR BANK 'A' - SPRAY-ON FIRE-PROOFING IN P.E. CARS 24, 25 & 26

ELEVATOR BANK B. CLEANING OF DEBRIS IN P.E. CARS 33, 34 & 35.

INSPECTOR	DATE	SHIFT		REVIEWED BY
Lou Dicadegna	12/29/70	8-4:30		CA

INSPECTOR'S DAILY NARRATIVE

CONTRACTOR	WEATHER
MARIO & DI BONO	COLD

'A'
BANK 'A' - SPRAY ON FIRE-[illegible] IN HATCHES # 24, 25 & 26
BANK 'B' - CLEANING IN # 33, 34 & 35.

'B' NO WORK - COLD WEATHER

[illegible] 12/31/70 DATE 8-4:30 SHIFT [illegible] REVIEWED BY [signature]

EXPERIMENTAL 8-68

INSPECTOR'S DAILY NARRATIVE

CONTRACT NO.	CONTRACTOR	WEATHER
113	Mario & Di Bono	

Tower B
5 Plasterers 5 Laborers in bar [illegible] of 169 [illegible]
2 plasterers in 332 w/
1 " in 310 / 2 labor.
Worked till 6 PM

[signature] INSPECTOR 12/31/70 DATE Day SHIFT [illegible] REVIEWED BY [signature]

G.A. SMITH

INSPECTOR'S DAILY NARRATIVE

CONTRACTOR	WEATHER
MARIO & DI BONO	COLD - SNOW

'A'
SPRAY-ON FIREPROOFING
CLEANING

'B'
NOT WORKING - COLD WEATHER

[illegible] 12/29/70 DATE 8-4:30 SHIFT [illegible] REVIEWED BY [signature]

EXPERIMENTAL 8-68

G.A. SMITH.

INSPECTOR'S DAILY NARRATIVE

CONTRACT NO.	CONTRACTOR	WEATHER
113	MARIO & DI BONO	COLD

TOWER 'A'
BANK 'A' SPRAYING FIREPROOFING.
BANK 'B' CLEANING

TOWER 'B'
NOT WORKING - COLD WEATHER.

[signature] INSPECTOR 12/30/70 DATE 8-4:30 SHIFT [illegible] REVIEWED BY [signature]

INSPECTOR'S DAILY NARRATIVE

CONTRACT NO.	CONTRACTOR	WEATHER
113	MARIO & DI BONO	SUNNY & COLD

TOWER A.

ELEVATOR BANK B - VACUUM CLEANING WITH A THREE CAR OPERATION.

TOWER 'B' NOT WORKING - COLD WEATHER

[signature] INSPECTOR — 1/6/71 DATE — 8-4:30 SHIFT — REVIEWED BY [signature]

Contract No.	Contractor	Weather
113	MARIO & DI BONO	SUNNY & COLD

TOWER 'A'

ELEVATOR BANK 'B' - VACUUM CLEANING THREE CAR OPERATION IN HATCHES 33, 34 & 35.

[signature] Inspector — 1/7/71 Date — 8-4:30 Shift — Reviewed by [signature]

C.A. SMITH

EXPERIMENTAL INSPECTOR'S DAILY NARRATIVE

~~C.A. SMITH~~

CONTRACT NO.	CONTRACTOR	WEATHER
113	MARIO & DI BONO	PARTLY-CLOUDY

TOWER 'A'

ELEVATOR BANK A - CLEANING OF OVER SPRAY FIREPROOFING MATERIAL FROM HATCHES 24, 25 & 26.

TOWER 'B'

SPRAY-ON FIRE PROOFING ON BAR JOISTS AND CORE COLUMNS ON THE 32ND AND 40TH FLOORS.

[signature] INSPECTOR — 1/5/71 DATE — 8-4:30 SHIFT — REVIEWED BY [signature]

EXPERIMENTAL INSPECTOR'S DAILY NARRATIVE

CONTRACT NO.	CONTRACTOR	WEATHER
113	MARIO & DI BONO	RAIN

TOWER 'A'

ELEVATOR BANK A & B - CLEANING OPERATION TAKING PLACE IN HATCHES 24, 25, 26, 33 34, & 35. CONTRARY TO A PREVIOUS AGREEMENT WITH TRCC THESE HATCHES ARE BEING CLEANED WITH A ONE CAR AT A TIME OPERATION INSTEAD OF THREE CARS SIMULTANEOUSLY.

1/5/71 F. GORRADO REPORTS THEY WILL HAVE "3 CAR OPERATION" STARTING 1/6/71.

[signature] INSPECTOR — 1/4/71 DATE — 8-4:30 SHIFT — REVIEWED BY [signature]

Contract No. 113 | Contractor: Mario & Di Bono | Weather:

Tower "B"

Cleaning Shafts of Bank "B" from 9 Floor down.

Inspector | Date: 1/11/71 | Shift: Day | Reviewed by

Contract No. 113 | Contractor: MARIO & DI BONO | Weather: FAIR & COLD

TOWER 'B'

FURNISHED AND INSTALLED SPRAY-ON FIREPROOFING ON BAR JOISTS AND WEB COLUMNS ON THE 31ST FLOOR.

Inspector | Date: 1/12/71 | Shift: 8-4:30 | Reviewed by

3033
6-70

INSPECTOR'S DAILY NARRATIVE

Contract No. 113 | Contractor: MARIO & DI BONO | Weather: COLD

TOWER 'A'

ELEVATOR BANK 'B' - CLEANING IN CARS 33, 34 & 35 - 3 CAR OPERATION. THESE HATCHES SHOULD BE COMPLETED BY 1/15/71.

TOWER 'B'

NOT WORKING · COLD WEATHER

Inspector | Date: 1/8/71 | Shift: 8-4:30 | Reviewed by

PA 3033
10-70

INSPECTOR'S DAILY NARRATIVE

Contract No. 113 | Contractor: MARIO & DI BONO | Weather: FAIR

TOWER 'A'

ELEVATOR BANK 'B' - CLEANING - 3 CAR OPERATION

TOWER 'B' - NOT WORKING - NO WATER

Inspector | Date: 1/11/71 | Shift: 8-4:30 | Reviewed by

Contract No. 113 | **Contractor** Mario & Di Bono | **Weather**

Truck – Patch walls Horiz. beams
310 to 332 level

Inspector [signature] | **Date** 1/13/71 | **Shift** Day | **Reviewed by** [initials]

Contract No. 113 | **Contractor** Mario & Di Bono | **Weather**

Cleaning Shaft Bank B & A
Subject touch up on Tenant
area floors due to duct
installation will start Friday
or Saturday when trades are
met on floors.

Inspector [signature] | **Date** 1/14/71 | **Shift** Day | **Reviewed by** [initials]

FA 3033 10-70

INSPECTOR'S DAILY NARRATIVE

Contract No. 113 | **Contractor** MARIO & DI BONO | **Weather** Cld.

TOWER 'A'
ELEVATOR BANK A – VACUUM CLEANING
3-CAR OPERATION.

ELEVATOR BANK 'B' · CARS – 33, 34 & 35.
INSPECTED SHAFTS THIS DATE &
FOUND ACCEPTABLE. TACC. TURNED
THESE SHAFTS OVER TO OTIS AT
12:00 NOON.

Inspector [signature] | **Date** 1/13/71 | **Shift** 8-4:30 | **Reviewed by** [initials]

FA 3033 10-70

INSPECTOR'S DAILY NARRATIVE

Contract No. 113 | **Contractor** MARIO & DI BONO | **Weather** RAIN

TOWER 'A'
ELEVATOR BANK 'A' - VACUUM CLEANING
- 3 CAR OPERATION

TOWER 'B' - NOT WORKING

Inspector [signature] | **Date** 1/14/71 | **Shift** 8-4:30 | **Reviewed by** [initials]

XIP-22

INSPECTOR'S DAILY NARRATIVE

10-70

Contract No.	Contractor	Weather
113	MARIO & DI BONO	COLD

TOWER 'B'

SPRAY-ON FIREPROOFING OF BAR JOISTS
AND CORE COLUMNS ON FLOORS 26,
31 & 32.

Inspector: Lou Guadagno [illegible] Date: 1/22/71 Shift: 8-4:30 Reviewed by: SFB [illegible]

INSPECTOR'S DAILY NARRATIVE

10-70

Contract No.	Contractor	Weather
113	Mario & Di Bono	

Tower A

2 cu Patch (17 Floor)
Safes disturbed by duct
work.

Inspector: [illegible] Date: 1/22/71 Shift: Day Reviewed by: SFB [illegible]

INSPECTOR'S DAILY NARRATIVE

FA 3033
10-70

Contract No.	Contractor	Weather
113	Mario & Di Bono	

Tower A

2 - mech, 2 labors patch
17 floor around
duct installation
3 - labors cleaning shafts
Both A & B

Inspector: [illegible] Date: 1/18/71 Shift: Day Reviewed by: SFB [illegible]

INSPECTOR'S DAILY NARRATIVE

FA 3033
10-70

Contract No.	Contractor	Weather
113	Mario & Di Bono	

Tower A

2 Mech - Patch 17 Fl. damage
2 " - Cleaning Shafts Both "B"

Inspector: [illegible] Date: 1/19/71 Shift: Day Reviewed by: SFB [illegible]

Contract No. 113 | Contractor: Mario & Di Bona | Weather:

2 on 19 Fl patch dist-urbed areas

2 on clean up

Inspector: [signature] | Date: 1/28/71 | Shift: Day | Reviewed by: [signature]

10-70

Contract No. 113 | Contractor: Mario & Di Bona | Weather:

Tower A

2 mech on 18 Fl patch disturbed areas.

Inspector: [signature] | Date: 1/27/71 | Shift: Day | Reviewed by: [signature]

PA 3033 10-70

INSPECTOR'S DAILY NARRATIVE

Contract No. 113 | Contractor: MARIO & DI BONA | Weather: COLD [illegible]

TOWER 'B'

FURNISHED AND INSTALLED CAFECO SEALER OVER CRACKED FIREPROOFING ON THE 40TH FLOOR.

Inspector: [signature] | Date: 1/26/71 | Shift: 8-4:30 | Reviewed by: [signature]

PA 3033 10-70

INSPECTOR'S DAILY NARRATIVE

Contract No. 113 | Contractor: Mario & Di Bona | Weather:

2 on 18 Fl cleanup

2 on 19 Fl touch up disturbed areas of these due to duct work.

Inspector: [signature] | Date: 1/29/71 | Shift: Day | Reviewed by: [signature]

PA 2030 (10-70)

YIP-22

INSPECTOR'S DAILY NARRATIVE

Contract No.	Contractor	Weather
WTC 113	Mario & DiBono / Scally	clear ...

2 men from Scally worked hours
overtime on exhaust ducts on elev.
294 SW of tower B
as per request of Tishman

Inspector	Date	Shift	Reviewed by
[illegible signature]	11/29/71	5-9	

XIP-42

INSPECTOR'S DAILY NARRATIVE

Contract No.	Contractor	Weather
113	ATLAS- PORT MORRIS	CLEAR

TOWER 'B'

FURNISHED AND INSTALLED SPRAY-ON FIRE PROOFING ON BAR JOISTS AND CORE COLUMNS AND ON THE 34TH & 35TH FLOORS

Inspector	Date	Shift	Reviewed by
[signature]	2/25/71	8-4:30	[signature]

INSPECTOR'S DAILY NARRATIVE

Contract No.	Contractor	Weather
113	MARIO & DI BONO	CLEAR

TOWER A

ELEVATOR BANK C. PATCH HOLES IN SHAFT #39

TOWER B

FURNISHED AND INSTALLED SPRAY-ON FIRE-PROOFING ON BAR JOISTS AND CORE COLUMNS ON THE 34TH 35TH & 36TH FLOORS

Inspector	Date	Shift	Reviewed by
[signature]	2/26/71	8-4:30	[signature]

INSPECTOR'S DAILY NARRATIVE

Contract No.	Contractor	Weather
113	MARIO & DI BONO	RAIN

TOWER 'A'

ELEVATOR BANK C. FURNISHED AND INSTALLED SPRAY-ON FIRE PROOFING IN SHAFTS 39, 40 & 41

Inspector	Date	Shift	Reviewed by
[signature]	2/5/71	8-4:30	[signature]

INSPECTOR'S DAILY NARRATIVE

Contract No.	Contractor	Weather
113	MARIO & DI BONO	CLD

TOWER A

ELEVATOR BANK C. SPRAY-ON FIRE-PROOFING IN SHAFTS 39, 40 & 41.
3-CAR. OPERATION

Inspector	Date	Shift	Reviewed by
[signature]	2/9/71	8-4:30	[signature]

PA 3033 10-70

INSPECTOR'S DAILY NARRATIVE

Contract No.	Contractor	Weather
113	MARIO & DI BONO	FAIR

TOWER 'A'
ELEVATOR BANK C - APPLICATION OF CAFECO SEALER IN SHAFTS 39, 40 & 41.

TOWER 'B'
INSTALLATION OF SPRAY-ON FIRE PROOFING ON THE 32nd FLOOR. OPERATION SHUT DOWN AT 11 AM BECAUSE OF LOW WATER PRESSURE.

Inspector: [signature] Date: 2/16/71 Shift: 8-4:30 Reviewed by: [initials]

10-70 XIP-22

INSPECTOR'S DAILY NARRATIVE

Contract No.	Contractor	Weather
113	Mario & De Bono	

Has gone as far as possible on patching (18 fl last) no duct in place on 19 fl

Inspector: [signature] Date: 2/18/71 Shift: Day Reviewed by: [initials]

PA 3033 10-70

INSPECTOR'S DAILY NARRATIVE

C. E. SMITH

Contract No.	Contractor	Weather
113	MARIO & DI BONO	FAIR

TOWER 'A'
ELEVATOR BANK C - APPLICATION OF CAFECO SEALER IN SHAFTS 39, 40 & 41.

TOWER 'B'
FURNISHED AND INSTALLED SPRAY-ON FIRE-PROOFING ON BAR JOIST'S AND CORE COLUMNS ON THE 32nd FLOOR.

Inspector: [signature] Date: 2/17/71 Shift: 8-4:30 Reviewed by: [initials]

PA 3033 10-70

INSPECTOR'S DAILY NARRATIVE

C. E. SMITH

Contract No.	Contractor	Weather
113	MARIO & DI BONO	FAIR

TOWER 'A'
ELEVATOR BANK C - APPLICATION OF CAFECO SEALER IN SHAFTS 39, 40 & 41.

TOWER 'B'
FURNISHED AND INSTALLED SPRAY-ON FIRE PROOFING ON BAR JOIST AND CORE COLUMNS ON THE 32nd FLOOR.

Inspector: [signature] Date: 2/18/71 Shift: 8-4:30 Reviewed by: [initials]

XIP-22

10-70

Contract No.	Contractor	Weather
113	MARIO & DI BONO	COLD

TOWER 'A'

ELEVATOR BANK C - SPRAY-ON FIREPROOFING IN SHAFTS 39, 40 & 41.

TOWER B.

NOT WORKING - COLD WEATHER

Inspector: [signature] Date: 2/10/71 Shift: [illegible] Reviewed by: [signature]

10-70

Contract No.	Contractor	Weather
113	MARIO & DI BONO	CLOUDY

TOWER A.

ELEVATOR BANK C - SPRAY-ON FIREPROOFING IN SHAFTS 39, 40 & 41.

TOWER 'B' - SPRAY-ON FIREPROOFING OF BAR JOISTS AND CORE COLUMNS ON THE 33RD FLOOR.

Inspector: [signature] Date: 2/8/71 Shift: Reviewed by: [signature]

PA 3033 10-70

INSPECTOR'S DAILY NARRATIVE

Contract No.	Contractor	Weather
113	MARIO & DI BONO	RAIN

TOWER 'A'

ELEVATOR BANK C - CLEANING IN SHAFTS 39, 40 & 41. - THREE CAR OPERATION.

TOWER 'B'

FURNISHED AND INSTALLED SPRAY-ON FIREPROOFING ON BAR JOISTS AND CORE COLUMNS ON THE 33RD FLOOR.

Inspector: [signature] Date: 2/23/71 Shift: [illegible] Reviewed by: [signature]

PA 3033 10-70

INSPECTOR'S DAILY NARRATIVE

Contract No.	Contractor	Weather
113	MARIO & DI BONO	RAIN

TOWER A.

ELEVATOR BANK C - CLEANING IN SHAFTS 39, 40 & 41 - 3 CAR OPERATION

TOWER B.

FURNISHED AND INSTALLED SPRAY-ON FIREPROOFING ON BAR JOISTS AND CORE COLUMNS.

Inspector: [signature] Date: 2/22/71 Shift: [illegible] Reviewed by: [signature]

YIP-22

10-70

INSPECTOR'S DAILY NARRATIVE

Contract No.	Contractor	Weather
113	MARIO & DI BONO	CLOUDY

TOWER A.

ELEVATOR BANK C. CLEANING - 3 CAR OPERATION.

TOWER "B"

FURNISHED AND INSTALLED SPRAYFON FIRE-PROOFING ON BAR JOISTS AND WIDE COLUMNS ON FLOORS 33, 34 & 36

Inspector	Date	Shift	Reviewed by
[signature]	2/29/71	8-4:30	[signature]

YIP-22

INSPECTOR'S DAILY NARRATIVE

10-70

Contract No.	Contractor	Weather
113.00	MARIO - DIBONO	CLEAR - MILD

TOWER 'A', NO SPRAY ON FIRE PROOFING TODAY
3 LABORERS CLEANING SHAFT # 39

Inspector: [illegible signature] — Date: 3-1-71 — Shift: 8AM to 4:30 PM — Reviewed by: [illegible signature]

INSPECTOR'S DAILY NARRATIVE

10-70

Contract No.	Contractor	Weather
113	MARIO & DI BONO	CLOUDY

TOWER 'B'

FURNISHED AND INSTALLED SPRAY-ON FIRE PROOFING OF [illegible] [illegible] AND CORE COLUMNS ON THE 37TH [illegible]
3 SPRAYERS AND 2 LABORERS

Inspector: [illegible signature] — Date: 3/24/71 — Shift: 8-4:30 — Reviewed by: [illegible signature] 4/9/71

INSPECTOR'S DAILY NARRATIVE

PA 3033 10-70

Contract No.	Contractor	Weather
113	MARIO & DI BONO	CLOUDY

TOWER 'B'

FURNISHED AND INSTALLED SPRAY-ON FIRE PROOFING ON THE 6TH FLOOR.

Inspector: [illegible signature] — Date: 3/19/71 — Shift: 8-4:30 — Reviewed by: [illegible signature] 3/12/71

INSPECTOR'S DAILY NARRATIVE

PA 3033 10-70

Contract No.	Contractor	Weather
113	MARIO & DI BONO	CLEAR

TOWER 'B'
FURNISHED AND INSTALLED SPRAY-ON FIRE-PROOFING ON THE FOLLOWING FLOORS:

39TH FLOOR - 3 SPRAYERS AND 2 LABORERS.

6TH FLOOR - 2 SPRAYERS AND 4 LABORERS

Inspector: [illegible signature] — Date: 3/18/71 — Shift: 8-4:30 — Reviewed by: [illegible signature] 3/23/71

10-70

Contract No.	Contractor	Weather
113	Mario & Di Bono	Clear

TOWER A
ELEVATOR BANK C. CLEANING & PATCHING
IN SHAFTS 39, 40, & 41.

TOWER B
NOT WORKING.

[signature] 3/5/71 8-4:30 [signature]
Inspector Date Shift Reviewed by

XIP-22

FA 3033
10-70

INSPECTOR'S DAILY NARRATIVE

Contract No.	Contractor	Weather
113	Mario & Di Bono	Cloudy

TOWER B

FURNISHED AND INSTALLED SPRAYED-ON
FIRE PROOFING ON THE 38TH FLOOR
AND MARK II SHAVING ON THE
6TH FLOOR.

[signature] 3/2/71 8-4:30 [signature]
Inspector Date Shift Reviewed by

FA 3033
10-70

INSPECTOR'S DAILY NARRATIVE

G.A. SMITH

Contract No.	Contractor	Weather
113	Mario & Di Bono	Rain

TOWER A.
ELEVATOR BANK C. CLEANING & PATCHING
SHAFTS 39, 40 & 41.

TOWER B: FURNISHED AND INSTALLED SPRAY
-ON FIRE PROOFING ON BAR JOISTS AND
CORE COLUMNS ON THE 37TH AND 38TH
FLOORS.

[signature] 3/3/71 8-4:30 [signature]
Inspector Date Shift Reviewed by

FA 3033
10-70

INSPECTOR'S DAILY NARRATIVE

G.A. SMITH

Contract No.	Contractor	Weather
113	Mario & Di Bono	Snow.

TOWER A.
ELEVATOR BANK C: CLEANING & PATCHING
IN SHAFTS 39, 40, & 41.

TOWER B NOT WORKING

[signature] 3/4/71 8-4:30 [signature]
Inspector Date Shift Reviewed by

XIP-22

10-70

Contract No.	Contractor	Weather
113	MARIO & DI BONO	CLOUDY

TOWER 'B'

FURNISHED AND INSTALLED SPRAY-ON FIRE PROOFING ON BAR JOISTS AND CORE COLUMNS ON THE FOLLOWING FLOORS:

39TH FLOOR - 3 SPRAYERS 2 LABORERS

6TH FLOOR - 3 SPRAYERS 2 LABORERS

Inspector: [signature] Date: 3/15/71 Shift: 8-4:30 [initials] Reviewed by: [signature] 3/18/71

10-70

Contract No.	Contractor	Weather
113	MARIO & DI BONO	CLOUDY

TOWER 'B'

FURNISHED AND INSTALLED SPRAY-ON FIREPROOFING ON BAR JOISTS AND CORE COLUMNS ON THE 35TH, 37TH & 38TH FLOORS.

Inspector: [signature] Date: 3/3/71 Shift: 8-4:30 [initials] Reviewed by: [signature]

PA 3033
10-70

INSPECTOR'S DAILY NARRATIVE

Contract No.	Contractor	Weather
113	MARIO & DI BONO	CLOUDY

TOWER 'B'

FURNISHED AND INSTALLED SPRAY-ON FIRE PROOFING ON THE FOLLOWING FLOOR:

6TH FLOOR - 4 SPRAYERS 2 LABORERS.

Inspector: [signature] Date: 3/17/71 Shift: 7-4:30 [initials] Reviewed by: [signature] 3/18/71

PA 3033
10-70

INSPECTOR'S DAILY NARRATIVE

Contract No.	Contractor	Weather
113	MARIO & DI BONO	CLEAR

TOWER 'B'

FURNISHED AND INSTALLED SPRAY-ON FIRE-PROOFING ON THE 6TH FLOOR - 4 SPRAYERS AND 2 LABORERS

Inspector: [signature] Date: 3/16/71 Shift: 8-4:30 [initials] Reviewed by: [signature] 3/18/71

XIP-22

INSPECTOR'S DAILY NARRATIVE

Contract No.	Contractor	Weather
113	MARIO & DI BONO	CLOUDY

TOWER 'B'

FURNISHED AND INSTALLED SPRAY-ON FIRE-PROOFING ON THE FOLLOWING FLOORS:

4TH FL. 3 SPRAYERS, 2 LABORERS

6TH FLOOR 2 SPRAYERS, 1 LABORER

Inspector: [signature] Date: 3/11/71 Shift: 8-4:30 Reviewed by: [signature]

INSPECTOR'S DAILY NARRATIVE

Contract No.	Contractor	Weather
113	MARIO & DI BONO	CLEAR

TOWER 'B'

TWO SPRAYERS AND FIVE LABORERS

FURNISHED AND INSTALLED SPRAY-ON FIRE PROOFING ON THE 6TH FLOOR.

Inspector: [signature] Date: 3/12/71 Shift: 8-4:30 Reviewed by: [signature]

PA 3033 10-70

INSPECTOR'S DAILY NARRATIVE

Contract No.	Contractor	Weather
113	MARIO & DI BONO	PARTLY CLOUDY

TOWER 'A'

ELEVATOR BANK C. CLEANING & PATCHING IN SHAFT # 59

TOWER 'B'

FURNISHED AND INSTALLED SPRAY-ON FIRE-PROOFING OF BAR JOISTS AND WIRE COLUMNS ON THE 34TH & 35TH FLOORS.

Inspector: [signature] Date: 3/1/71 Shift: 8-4:30 Reviewed by: [signature]

PA 3033 10-70

INSPECTOR'S DAILY NARRATIVE

Contract No.	Contractor	Weather
113	Mario & Di Bono	

Tower A

83 Fl. Bar joists

2 Plasterers & 2 Laborers

Shaft Part patch work C/X.

Work in 3/31/71

Inspector: [signature] Date: 3/31/71 Shift: Day Reviewed by: [signature] 4/2/71

XIP-22 DAILY NARRATIVE

CONTRACT NO.	CONTRACTOR	WEATHER
WTC. 113.00 SA.#3	Spray On Fireproofing (Mario & DiBono)	CLOUDY

N.E. PLAZA BLDG. PAGE 1 of 2

PROGRESS REPORT ON SPRAY-ON FIREPROOFING

10TH FL. CEILING - NO SPRAY-ON FIREPROOFING APPLIED TO DATE

9TH FL. " - " " " " " " "

8TH FL. " APPROX. 98% COMPLETE ELEV. BEAMS & COLS. AND OUTER PERIMETER CHANNELS NEED FIREPROOFING.

7TH FL " " 97% " (SAME AS 8TH FL) · SOME BEAM SOFFITS NEED RE-SPRAY

6TH FL " " 98% " (SAME AS 8TH FL)

5TH FL. " " 80% " CONTRACTOR APPLYING SPRAY-ON FIREPROOFING

4TH FL " " 97% " (SAME AS 7TH FL)

(CONTINUED PAGE 2)

R. J. Meary — INSPECTOR | 4/5/71 — DATE | 8 to 430 — SHIFT | [initials] — REVIEWED BY

DAILY NARRATIVE

CONTRACT NO.	CONTRACTOR	WEATHER
WTC. ~~[illegible]~~ 113 SA.#3	~~DIC-UNDERHILL~~	CLOUDY

N.E. PLAZA BLDG. PAGE 2 of 2

3RD FL. CEILING APPROX 30% COMPLETE: CONTRACTOR SETTING UP TARPS.

2ND FL. " " 20% "

MAIN FL " " 30% "

R. J. Meary — INSPECTOR | 4/5/71 — DATE | 8 to 430 — SHIFT | [initials] — REVIEWED BY

PA 3033 10-70

INSPECTOR'S DAILY NARRATIVE

Contract No.	Contractor	Weather
113	Mario & DiBono	

Tower A

4/ Spray on 84 ft. by panels.

Note: Some patch work started on 19 ft & 20 ft approx 80% work [illegible]

[signature] — Inspector | 4/30/71 — Date | [illegible] — Shift | [illegible] — Reviewed by

---

EXPERIMENTAL 6-68

INSPECTOR'S DAILY NARRATIVE

CONTRACT NO.	CONTRACTOR	WEATHER
WTC ~~[illegible]~~ 113	DIC-UNDERHILL	CLEAR

N.E. PLAZA BLDG.

Mario-DiBono working (spraying) on 3rd fl.

Sheet metal men (3 men worked ½ day) and water proofers worked flashing & waterproofing Subway Entrance.

Excavators cleaned floor at elev. 296 of the yesterday's [illegible]. The excavators also capped off each well point pipe and continued chipping the concrete floor slab at the well point locations. (However the contractor was instructed by Bob Albright to chip floor no deeper than 6")

R. J. Meary — INSPECTOR | 4/9/71 — DATE | 8 to 430 — SHIFT | [initials] — REVIEWED BY

10-70

INSPECTOR'S DAILY NARRATIVE

Contract No.	Contractor	Weather
WTC 113.00	MARIO · DI BONO	CLEAR - MILD

SPRAY-ON FIRE PROOFING

NO WORK T/B THIS CONTRACT UNTIL FURTHER NOTICE

C. Zuelling — 4-13-71 — 8AM-4:30PM — [initials] — 4/21/71

Inspector — Date — Shift — Reviewed by

PA 3033
10-70

YIP-98 INSPECTOR'S DAILY NARRATIVE

Contract No.	Contractor	Weather
WTC 113.00	Mario & Di Bono	Sunny - Mild

Tower "B"

106th Floor - spraying bar joists

NOTE: Contractor is not patching bar joist fireproofing from 54th floor up - (lack of small spray machines)

R. Vreeland — 4/27/71 — 8-4:30 — [initials]/EB

Inspector — Date — Shift — Reviewed by

PA 3033
10-70

INSPECTOR'S DAILY NARRATIVE

Contract No.	Contractor	Weather
113	ABBOTT & COMMERCE	CLEAR

TOWER 'B'

ONE FOREMAN AND FOUR MECHANICS

FURNISHED AND INSTALLED THREE-PLY

MEMBRANE WATERPROOFING 40% COMPLETE

[signature] — 4/20/71 — 8-4:30 — [initials] — 4/20/71

Inspector — Date — Shift — Reviewed by

PA 3033
10-70

INSPECTOR'S DAILY NARRATIVE

Contract No.	Contractor	Weather
113	Mario & Di Bono	

3/83 FE bar joints

[signature] — 4/20/71 — [illegible] — [initials] — 4/21/71

Inspector — Date — Shift — Reviewed by

YIP-22

PA 3033 10-70

INSPECTOR'S DAILY NARRATIVE

Contract No. 113 | Contractor Mario & Di Bono | Weather

1/4 Spray fire proofing on 86 & 88
83 floor 98% complete
84 95% Shanty holding up
complete
85 - 95%
Start ... on ... attached
... lower floors

Inspector ... Date 5/6/71 Shift Day ... Reviewed by ... 5/11/71

PA 3033 10-70

INSPECTOR'S DAILY NARRATIVE

Contract No. 113 | Contractor MARIO & DI BONO | Weather CLEAR

TOWER 'B'

THE SPRAYERS & ONE HAMMER
FURNISHED & INSTALLED SPRAY-ON
FIRE PROOFING ON BAR JOISTS & CORE
COLUMNS ON THE 37TH FLOOR - 80% COMPLETE

Inspector ... Date 5/5/71 Shift ... Reviewed by ... 5/11/71

PA 3033 10-70

INSPECTOR'S DAILY NARRATIVE

Contract No. 113 | Contractor Mario & Di Bono | Weather

4 plasters on 84-85 bar joists

Inspector ... Date 5/3/71 Shift Day ... Reviewed by ... 5/11/71

PA 3033 10-70

INSPECTOR'S DAILY NARRATIVE

Contract No. 113 | Contractor Mario & Di Bono | Weather

84 ... ...
4 plasters 2 ...

Inspector ... Date ... 71 Shift Day ... Reviewed by ... 5/5/71

XIP-22

DAILY NARRATIVE

CONTRACT NO.	CONTRACTOR	WEATHER
WTC 113.00	MARIO + DI BONO	CLEAR

N.E. PLAZA BLDG.

Continued application of spray-on fireproofing to beams + soffits at elev. 310 ceiling level. Also sprayed the beams along the cantilevered areas at the south, west + north sides of the Bldg. 3rd fl. Also removed spray-on fireproofing (by brooming) from the ceiling (conc. areas only) of the 8th fl.

Sunday

Inspector: R. [illegible] — Date: 5/1/71 — Shift: 8 to 4:30 — Reviewed by: [illegible]

DAILY NARRATIVE

CONTRACT NO.	CONTRACTOR	WEATHER
WTC 113.00	MARIO + DI BONO	CLOUDY

N.E. PLAZA BLDG.

Contractor continued application of spray-on fireproofing to beams + soffits at elev. 310 ceiling. Also sprayed the beams along the cantilevered areas at the north + west sides of the Bldg 3rd fl. Also cont'd removal of spray-on material (by brooming) from ceiling (conc. areas only) of the 8th fl.

Sunday

Inspector: R. [illegible] — Date: 5/2/71 — Shift: 8 to 4:30 — Reviewed by: [illegible]

PA 3032 10-70

INSPECTOR'S DAILY NARRATIVE

Contract No.	Contractor	Weather
113	MARIO + DI BONO	CLEAR

TOWER 'B'

TWO SPRAYERS + ONE MIXER

FURNISHED + INSTALLED SPRAY-ON FIRE-PROOFING ON BAR JOIST + CORE COLS. ON THE 37TH FLOOR. 90% COMPLETE.

Inspector: Lou [illegible] — Date: 5/7/71 — Shift: 8-4:30 — Reviewed by: [illegible] 5/7/71

PA 3032 10-70

INSPECTOR'S DAILY NARRATIVE

Contract No.	Contractor	Weather
113	MARIO + DI BONO	PARTLY CLOUDY

TOWER 'A'

BANK 'D' ZONE I SHAFTS 44, 45 + 46

FURNISHED + INSTALLED SPRAY-ON FIRE-PROOFING ON STRUCTURAL STEEL COLUMNS + H-BEAMS. FLOORS 1-40.

Inspector: Lou [illegible] — Date: 5/13/71 — Shift: 8-4:30 — Reviewed by: [illegible] 5/17/71

PA 3033 10-70 INSPECTOR'S DAILY NARRATIVE

YIP-22

Contract No. 113
Contractor: Mario & Di Bono
Weather:

Tower A
4/89 floor bar - finish
tenant area -
18 FL : 100% } patch disturbed
19 FL : 95% } areas of other
20 FL : 100% } trades.
21 FL : 100% }
22 FL : 50%

Inspector: [signature] Date: 5/17/71 Shift: Day Reviewed by: [initials] CAK 5/17/71

PA 3033 10-70 INSPECTOR'S DAILY NARRATIVE

Contract No. 113
Contractor: MARIO & DI BONO
Weather: RAIN

TOWER 'A'

BANK 'D' ZONE I SHAFTS 44 45 & 46

INSTALLATION OF SPRAY-ON FIREPROOFING - FLOOR
1-40 2 SPRAYERS

Inspector: [signature] Date: 5/13/71 Shift: 8-4 PM Reviewed by: [initials] CAK 5/17/71

PA 3033 10-70 INSPECTOR'S DAILY NARRATIVE

Contract No. 113
Contractor: Mario & Di Bono
Weather:

Tower A.
1/4 on 89 FL - bar finish -
will work this PM
22 FL patch disturbed
areas.

Inspector: [signature] Date: 5/19/71 Shift: Day Reviewed by: [initials] CAK 5/20/71

PA 3033 10-70 INSPECTOR'S DAILY NARRATIVE

Contract No. 113
Contractor: MARIO & DI BONO
Weather: CLEAR

TOWER 'A'

FURNISHED & INSTALLED SPRAY-ON FIRE-
PROOFING OF STRUCTURAL STEEL IN ELEVATOR
BANK D ZONE I SHAFTS 44 45 & 46.
ONE SPRAYER & ONE LABORER

Inspector: [signature] Date: 5/14/71 Shift: 8-4 PM Reviewed by: [initials] CAK 5/14/71

Contract No. 113 | Contractor MARIO & DI BENO | Weather CLEAR

TOWER 'A'

BANK D, ZONE I SHAFTS 44, 45 & 46
FURNISHED & INSTALLED SPRAY-ON FIRE-PROOFING OF STRUCTURAL STEEL COLUMNS & BEAMS - ONE SPRAYER & ONE LABORER

Inspector [signature] Date 5/18/71 Shift 8-4:30 Reviewed by [initials] 5/21/71

PA 3033 10-70

YIP-22

INSPECTOR'S DAILY NARRATIVE

Contract No. 113 | Contractor MARIO & DI BENO | Weather CLEAR

TOWER 'A'
BANK 'A' ZONE II SHAFTS 54, 55 & 56
FURNISHED & INSTALLED SPRAY-ON FIRE PROOFING OF STRUCTURAL STEEL BEAMS & COLUMNS

TOTAL WORK FORCE - 1 SPRAYER & 1 LABORER.

Inspector [signature] Date 5/19/71 Shift 8-4:30 Reviewed by [initials] 5/21/71

PA 3033 10-70

INSPECTOR'S DAILY NARRATIVE

Contract No. 113 | Contractor MARIO & DI BENO | Weather CLEAR

TOWER 'A'
BANK A, ZONE II SHAFTS 54, 55 & 56
BANK D, ZONE I SHAFTS 44, 45 & 46

FURNISHED & INSTALLED CAFCO SPRAY-ON FIRE PROOFING OF STRUCTURAL STEEL BEAMS & COLUMNS.

2 SPRAYERS & 2 LABORERS

Inspector [signature] Date 5/17/71 Shift 8-4:30 Reviewed by [initials] 5/21/71

PA 3033 10-70

INSPECTOR'S DAILY NARRATIVE

Contract No. 113 | Contractor Mario & Di Beno | Weather

1 Man cleaning 22 fl. Tower A
floor coated with debris
4 1/2 fl. on bar joists —

Inspector [signature] Date 5/20/71 Shift Day Reviewed by [initials] 5/21/71